



AUG 2 1978

1. Federal Building, U.S. Post Office and Courthouse
2. Fairbanks, Alaska
3. Photographer: Victoria L. Taylor
4. Date of Photographs: July 20, 1977
5. Negatives located at GSA Center, Auburn, WA 98002
6. View: Taken from top floor of Polaris Building with telephoto lens. East (front) face (on Cushman Street) of Federal Building shown plus oblique view of north face (on Second Avenue). Camera direction: pointed west southwest.
7. 77-7-1-19

MAY 22 1978



AUG 2 1978

1. Federal Building, U.S. Post Office and Courthouse
2. Fairbanks, Alaska
3. Photographer: Victoria L. Taylor
4. Date of Photograph: July 20, 1977
5. Negatives located at GSA Center, Auburn, WA 98002
6. West (rear) (Turner Street) face of Federal Building, showing delivery entrance. Camera direction: pointed east.
7. 77-7-1-9

MAY 2 1978



1. Federal Building, U.S. Post Office and Courthouse
2. Fairbanks, Alaska
3. Photographer: Victoria L. Taylor
4. Date of Photograph: July 20, 1977
5. Negatives located at GSA Center, Auburn, WA 98002
6. Oblique view of east (front) (Cushman Street) face of Federal Building, with partial view of north (Second Avenue) face. Camera direction: pointed south southwest.
7. 77-7-1-6

MAY 22 1978



1. Federal Building, U.S. Post Office and Courthouse
2. Fairbanks, Alaska
3. Photographer: Victoria L. Taylor
4. Date of Photograph: July 20, 1977
5. Negatives located at GSA Center, Auburn, WA 98002
6. Two of three sets of entry doors, showing green marble panels above doors, aluminum grooved ornamentation, and aluminum transom grills (eagles). Camera direction: pointed southwest.
7. 77-7-1-4

MAY 22 1978





1. Federal Building, U.S. Post Office and Courthouse
2. Fairbanks, Alaska
3. Photographer: Victoria L. Taylor
4. Date of Photograph: July 20, 1977
5. Negatives located at GSA Center, Auburn, WA 98002
6. Courtroom ceiling, third floor of Federal Building, showing ornate plaster coffer ceiling. Camera direction: pointed east southeast.
7. 77-7-1-1

MAY 22 1978



1. Federal Building, U.S. Post Office and Courthouse
2. Fairbanks, Alaska
3. Photographer: Victoria L. Taylor
4. Date of Photograph: July 20, 1977
5. Negatives located at GSA Center, Auburn, WA 98002
6. Postal lobby on first floor of the Federal Building showing wood pilasters, bronze lock boxes, wrought iron grillwork, marble border and base to flooring. Camera direction: pointed northwest.
7. 77-7-1-15A

MAY 22 1978