



HILLSIDE

Natchez, Adams County, Mississippi

Looking northerly, the southerly  
facade during restoration.

Mary W. Miller, Historic Natchez  
Foundation, March 1985

Photo 1 of 5



HILLSIDE

Natchez, Adams County, Mississippi

Looking northerly, the hallway partition wall with doorway filled with four-leaf hinged doors.

Mary W. Miller, Historic Natchez Foundation,  
March 1985

Photo 2 of 5

2/17/87



HILLSIDE


Natchez, Adams County, Mississippi

Looking southeasterly, the mantel piece  
of the western rear room.

Mary W. Miller, Historic Natchez Foundation,  
March 1985

Photo 3 of 5

3/17/85



HILLSIDE

Natchez, Adams County, Mississippi

Looking southeasterly, the original  
closet of the western rear room.

Mary W. Miller, Historic Natchez Foundation,  
March 1985

Photo 4 of 5

3/17 (8)





HILLSIDE

Natchez, Adams County, Mississippi

Looking northwesterly, the southerly facade  
and easterly side elevation. Porch repaired.

Ken P'Pool, Mississippi Department of  
Archives and History, October 1986

Photo 5 of 5

3/17/87