



143-7809/8-24-16B1-35 5)

Photo #1

Pilgrim Holiness Church

Arthur, Arthur County, Nebraska

South-southeast facades

Photo by Janet Jeffries Spencer, 1978

Nebraska State Historical Society 7809/8:24

MAY 10 1979

JUN 18 1979



143 - 7809/8-21 1281 ~30 51

Photo #2

MAY 10 1979

Pilgrim Holiness Church

Arthur, Arthur County, Nebraska

South facade

JUN 18 1979

Photo by Janet Jeffries Spencer, 1978

Nebr. State Historical Society 7809/8:21



143-7809/8-19 1487-35.51

Photo #3
Pilgrim Holiness Church
Arthur, Arthur County, Nebraska
South and west facades
Photo by Janet Jeffries Spencer, 1978
Nebr. State Historical Society 7809/8:19

MAY 10 1979
JUN 18 1979



Photo #4 JUN 18 1979 MAY 10 1979
Pilgrim Holiness Church
Arthur, Arthur County, Nebraska
North and east facades
Photo by Janet Jeffries Spencer, 1978
Nebr. State Historical Society 7809/8:30

143-7809/8-30 1732-30 51



143 - 7809/8 16B2-35 S

Photo #5 JUN 18 1979 MAY 10 1979
Pilgrim Holiness Church
Arthur, Arthur County, Nebraska
interior looking north
Photo by Janet Jeffries Spencer, 1978
Nebr. State Historical Society 7809/8:33

5



193-780918-37 12B2-30 51

Photo #6 JUN 18 1979 MAY 10 1979
Pilgrim Holiness Church
Arthur, Arthur, County, Nebraska
Interior looking south toward vestibule
Photo by Janet Jeffries Spencer, 1978
Nebr. State Historical Society 7809/8:37

6

CONSTRUCTION

This building was made with wattle-daub
of rice straw. The poles were laid like tracks. Then they
were plastered with mud from a special lake. Then a coat
of mud plaster was put on for a more permanent finish.
The purpose of this type material was to keep the
cool low. But doors and windows had to be freighted by
teams from the railroad.



4

Photo #7.

Pilgrim Holiness Church

Arthur, Arthur County, Nebraska

Interior view-west wall showing structure

Photo by Janet Jeffries Spencer, 1978

Nebr. State Historical Society 7809/8:31

MAY 10 1979
JUN 18 1979

143 7809/8-30 1283-30 51