



Kelso Bowstring Arch Truss Bridge

Kelso vicinity, Lincoln Co., Tennessee

Photographer: George Fielder

Date: November 1981

Negative: Tennessee Historical Commission

View: Facing northwest

1 of 6

**BRIDGE  
CONDEMNED**  
Travel At Your Own Risk  
Under No Warranty



Kelso Bowstring Arch Truss Bridge

Kelso vicinity, Lincoln Co., Tennessee

Photographer: George Fielder

Date: November 1981

Negative: Tennessee Historical Commission

View: north portal

2 of 6



Kelso Bowstring Arch Truss Bridge

Kelso vicinity, Lincoln Co., Tennessee

Photographer: George Fielder

Date: November 1981

Negative: Tennessee Historical Commission

View: west elevation

3 of 6

**BRIDGE  
CONDEMNED**

Travel At Your Own Risk

See It In Williamsport, Pa.



Kelso Bowstring Arch Truss Bridge

Kelso vicinity, Lincoln Co., Tennessee

Photographer: George Fielder

Date: November 1981

Negative: Tennessee Historical Commission

View: facing south east; detail of arch

and vertical hangers.

4 of 6





Kelso Bowstring Arch Truss Bridge

Kelso vicinity, Lincoln Co., Tennessee


Photographer: George Fielder

Date: November 1981

Negative: Tennessee Historical Commission

View: Detail of north west corner bearing  
plate and bottom chord connection

5 of 6



Kelso Bowstring Arch Truss Bridge

Kelso vicinity, Lincoln Co., Tennessee

Photographer: George Fielder

Date: November 1981

Negative: Tennessee Historical Commission

View: facing east; west elevation of  
south abutment and wing wall

6 of 6