



JAMES OWENS FARM

AA-247

Anne Arundel County, Maryland

Photo: Donna Ware

Negative location: Maryland

Historical Trust

June 1986

(S.E. elev.)

Dwelling: Facade, looking S.W.

1/32



JAMES OWENS FARM

AA-247

Anne Arundel County, Maryland

Photo: Donna Ware

Negative location: Maryland

Historical Trust

June 1986

Dwelling: Facade, S.E. Elev.

2/32





James Owens Farm AA-247

Anne Arundel Co., MD

Photo: Donna Ware

Negative location: Maryland Historical Trust

June 1986

Dwelling: Facade, S.E. elev.

3/32



JAMES OWENS FARM

AA-247

Anne Arundel County, Maryland

Photo: Donna Ware

Negative location: Maryland

Historical Trust

June 1986

Dwelling: *Rear, W,*  
~~Rear~~ N. ~~E.~~ Elev.

4/32



JAMES OWENS FARM

AA-247

Anne Arundel County, Maryland

Photo: Donna Ware

Negative location: Maryland

Historical Trust

June 1986

Dwelling: ~~West~~<sup>E.</sup> N.W. Elev.

5/32



JAMES OWENS FARM

AA-247

Anne Arundel County, Maryland

Photo: Donna Ware

Negative location: Maryland

Historical Trust

June 1986

Terraced garden, looking N.W.

C/32





JAMES OWENS FARM

AA-247

Anne Arundel County, Maryland

Photo: Donna Ware

Negative location: Maryland

Historical Trust

June 1986

Interior: Principal entrance,  
looking S.E.

7/32





Something went wrong while we were encoding this page.  
Please check the log file to find out the details.



JAMES OWENS FARM

AA-247

Anne Arundel County, Maryland

Photo: Donna Ware

Negative location: Maryland

Historical Trust

June 1986

Interior: 1st flr entrance hall  
door looking N.W.

9/32



JAMES OWENS FARM

AA-247

Anne Arundel County, Maryland

Photo: Donna Ware

Negative location: Maryland

Historical Trust

June 1986

Inter: 1st flr entrance hall doorway looking S.E. from stair hall

10/32





JAMES OWENS FARM

AA-247

Anne Arundel County, Maryland

Photo: Donna Ware

Negative location: Maryland

Historical Trust

June 1986

Interior: 1st floor stair,  
looking west

11/32



JAMES OWENS FARM

AA-247.

Anne Arundel County, Maryland

Photo: Donna Ware

Negative location: Maryland

Historical Trust

June 1986

Inter: 1st flr door from entrance  
hall to S.E. room, looking N.E.

12/32



JAMES OWENS FARM

AA-247

Anne Arundel County, Maryland

Photo: Donna Ware


Negative location: Maryland

Historical Trust

June 1986

Interior: 1st floor S.E. room,  
looking S.W.

13/32



JAMES OWENS FARM

AA-247

Anne Arundel County, Maryland

Photo: Donna Ware

Negative location: Maryland

Historical Trust

June 1986

Interior: plaster ceiling medal-  
lion in 1st flr S.E. room

14/32





JAMES OWENS FARM

AA-247

Anne Arundel County, Maryland

Photo: Donna Ware

Negative location: Maryland

Historical Trust

June 1986

Interior: 1st flr S.E. room with  
bay window looking N.E.

15/32



JAMES OWENS FARM

AA-247.

Anne Arundel County, Maryland

Photo: Donna Ware


Negative location: Maryland

Historical Trust

June 1986

Int: detail of pressed brass valance  
in 1st flr S.E. rm, looking S.E.

16/32



JAMES OWENS FARM

AA-247

Anne Arundel County, Maryland

Photo: Donna Ware

Negative location: Maryland

Historical Trust

June 1986

Inter: plaster ceiling medallion  
in 1st flr rear wing N.E. room

17/32



JAMES OWENS FARM

AA-247

Anne Arundel County, Maryland

Photo: Donna Ware

Negative location: Maryland

Historical Trust

June 1986

Interior: 2nd floor, segmental  
arch doorway, looking S.E.

---

18/32





JAMES OWENS FARM

AA-247

Anne Arundel County, Maryland

Photo: Donna Ware

Negative location: Maryland

Historical Trust

June 1986

Interior: detail of 2nd floor  
doorway, looking S.E.

19/32



JAMES OWENS FARM

AA-247

Anne Arundel County, Maryland

Photo: Donna Ware

Negative location: Maryland

Historical Trust

June 1986

Inter: 2nd flr mantel in S.E. rm.  
of main block, looking S.W.

---

20/32



JAMES OWENS FARM

AA-247

Anne Arundel County, Maryland

Photo: Donna Ware

Negative location: Maryland

Historical Trust

June 1986

Tobacco barn, S.E. Elev. & N.E.  
gable end

21/32



JAMES OWENS FARM

AA-247

Anne Arundel County, Maryland

Photo: Donna Ware

Negative location: Maryland

Historical Trust

June 1986

Tobacco barn, N.W. Elev.

22/32





JAMES OWENS FARM

AA-247

Anne Arundel County, Maryland

Photo: Donna Ware

Negative location: Maryland

Historical Trust

June 1986

Cornhouse, S.W. gable end

23/32



JAMES OWENS FARM

AA-247

Anne Arundel County, Maryland

Photo: Donna Ware

Negative location: Maryland

Historical Trust

June 1986

Cornhouse, detail of tilted false  
plate N.W. Elev.

24/32



JAMES OWENS FARM . . . . . AA-247

Anne Arundel County, Maryland

Photo: Donna Ware

Negative location: Maryland

Historical Trust

June 1986

Kitchen/quarter, S.E. Elev.

25/32



JAMES OWENS FARM

AA-247

Anne Arundel County, Maryland.

Photo: Donna Ware

Negative location: Maryland

Historical Trust

June 1986

Looking N.E. toward dwelling &  
kitchen/quarter

26/32





JAMES OWENS FARM

AA-247

Anne Arundel County, Maryland

Photo: Donna Ware

Negative location: Maryland

Historical Trust

June 1986

Cornhouse, N.E. gable end

27/32



JAMES OWENS FARM

AA-247

Anne Arundel County, Maryland

Photo: Donna Ware

Negative location: Maryland

Historical Trust

June 1986

Kitchen/quarter, looking south

28/32



JAMES OWENS FARM

AA-247

Anne Arundel County, Maryland

Photo: Donna Ware

Negative location: Maryland

Historical Trust

June 1986

Kitchen/quarter, interior stove,  
looking S.W.

29/32



JAMES OWENS FARM

AA-247

Anne Arundel County, Maryland

Photo: Donna Ware

Negative location: Maryland

Historical Trust

June 1986

Carriage house, S.E. gable end

30/32





JAMES OWENS FARM

AA-247

Anne Arundel County, Maryland

Photo: Donna Ware

Negative location: Maryland

Historical Trust

June 1986

Chicken house (right), Meathouse  
(left), rear N.W. Elev.

31/32



JAMES OWENS FARM

AA-247

Anne Arundel County, Maryland

Photo: Donna Ware

Negative location: Maryland

Historical Trust

June 1986

Chicken house (left) & Meathouse,  
S.E. Elev.

32/32