# **United States Department of the interior** National Park Service

### National Register of Historic Places Continuation Sheet

Sect	ion number	_ Page					
		SUPP	LEMENTARY I	ISTING	RECORD		
	NRIS Referenc	e Number:	91001955	Date	Listed:	1/13/92	
	Fracas Lookou Property Name						
	Coconino County	<u>AZ</u> State					
	National Fore Multiple Name	st Fire L	ookouts in	the Sou	thwester	n Region !	<u>rr</u>
	This property Places in accomplete to the notwithstanding in the nominal	ordance wa e following the Nati	ith the attaing exception tional Park	ached nas, exc	ominatio lusions,	on document or amenda	tation ments,
fn	Signature of	the Keeper	r		<u>lla</u> Dat	3/42 te of Actio	on
	Amended Items	in Nomina	ation:		<b></b>		an anj sist anj sist sist inp sist ini anj sist sist sist sist sis
	Statement of Significance: Under Areas of Significance, Engineering is added.						
	This informat Forest Service		onfirmed wi	th Evan	DeBlooi	s of the T	u.s.
	DISTRIBUTION: National Nomination	Register ng Author:	property faity (withou	ile t nomin	ation at	tachment)	

## NATIONAL REGISTER OF HISTORIC PLACES REGISTRATION FORM

1955

1. Name of Property	
historic name Fracas Lookout Tree	
other names/site number AR-03-07-03	-1037
2. Location	
street & number N/A	/ /not for publication
city, town Fredonia	/ x/vicinity
state Arizona code AZ cou	nty Coconino code 005 zip code 86022
3. Classification	
Ownership of Property Category of P	
- private building( public-local public-State	- · · · · · · · · · · · · · · · · · · ·
public-local district	buildings
public-State x site	sites
$ \mathbf{x} $ public-Federal structure	structures
_  object	objects
N 0 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Total
Name of related multiple property lis	<del>-</del>
NAMIONAL PODDOM BIDD LOOKOVING IN MUD	previously listed in the National
NATIONAL FOREST FIRE LOOKOUTS IN THE	Register 0
SOUTHWESTERN REGION, USDA FOREST SERV	
4. State/Federal Agency Certification	1
	National Winterio Description Act of 1066
	he National Historic Preservation Act of 1966,
	his   nomination   request for determination
	ion standards for registering properties in the
	s and meets the procedural and professional
	rt 60. In my opinion, the property meets
	ter criteria. See continuation sheet.
Signature of certifying official	7-30-91 Date
Signature of Certifying Official	Date
USDA - Forest Service	
USDA - FOREST SERVICE	
In my opinion the property M meets	does not meet the National Register
criteria,   See continuation sheet	luces not meet the National Register
criteria, j_jsee contingation sheet	4/8/91
Signature of certifying official	n Date ' '
Signatura of the Market Market	evation Office
State Historic Preservation Office	,5004,01. <del>91</del> .44
5. National Park Service Certificati	on
I, hereby, certify that this property	
entered in the National Register.	·
	utravicote of Cec 1/13/92
determined eligible for	1/13/172
the National Register.	
, <del></del> ,	
See continuation sheet.	
_ determined not eligible for	
the National Register.	
_ removed from the National	
Register.	
other, (explain:)	
<del></del>	Detail O Anti-
₩ <sup>Sig</sup>	nature of the Keeper Date of Action
1	

6. Function or Use	
Historic Functions (enter categories	Current Functions (enter categories
from instructions	from instructions)
GOVERNMENT/ Lookout Facility	VACANT/NOT IN USE
7. Description	
Architectural Classification	Materials enter categories from
(enter categories from instructions)	instructions)
N/A	foundation
	walls
	roof
	other N/A

Describe present and historic physical appearance.

#### Summary

This isolated historic lookout tree is located on Fracas Ridge near Warm Springs Canyon on the North Kaibab Ranger District, Kaibab National Forest. It is within a Ponderosa pine forest on the Kaibab Plateau at an elevation of 8,160 feet. It is in good condition and retains sufficient integrity to qualify for National Register listing.

#### Physical Description

This lookout tree is a straight mature Ponderosa pine approximately 100 feet high and 3 feet in diameter with a ladder constructed up its eastern side. Six segments of ladder works remain. The lower 12-15 feet of the ladder have been removed. The remaining ladder is in good condition. The construction is typical of other ladders on lookout trees:  $2" \times 4"$  sidepieces with  $1" \times 12-14"$  crosspieces. The lookout tree never had a platform.

Immediately to the east of the tree and at its bottom is a brass cap  $(8 \times 8")$  set into a concrete and rock patch. The inscription reads "U.S. Dept. of Ag. Forest Service Visible Area Map Point Fire Control Fracas Ridge 10-6-1937".

#### Setting

Vegetation surrounding the site currently consists of a few small Ponderosa pines with some grasses and forbs. The entire area is heavily littered with duff and pine cones. It was logged last year (1989) and much debris remains. However, the setting retains much of its historic appearance. A large sinkhole is about 80 meters to the northeast of the tree.

#### Integrity

The Fracas Lookout Tree is still in good condition, despite having been abandoned for approximately 40 years. Only the lower 15 feet of ladder has been removed, for safety purposes. It is still readily identifiable as a lookout tree facility and thus retains the level of integrity defined in the continuation sheet.

8. Statement of Significance		
Certifying official has considered the sig	mificance of this property	in relation to
other properties:		1701
_ n	nationally     statewide	v  locally
Applicable National Register Criteria $ \overline{x} $ A	'  _ B   <u>x</u>  C  _ D	
Criteria Considerations (Exceptions)	.  _ B  _ C  _ D  _ E  _ F	_ G
Areas of Significance (enter categories	Period of Significance S	_
from instructions)		Dates
Conservation		
Politics/Government	1905-1940	1937
	Cultural Affiliation	
	N/A	
Significant Person	Architect/Affiliation	

State significance of property, and justify criteria, criteria considerations, and areas and periods of significance noted above.

#### Summary

Fracas Lookout Tree is significant under Criterion A [36 CFR 60.6] for its association with 1) the development of forest fire prevention, detection, and control by the USDA Forest Service between 1905 and 1940, and 2) the conservation movement and its influence on public land management from 1905 to 1940. It is also significant under Criterion C [36 CFR 60.6] because it embodies the distinctive characteristics of a type of construction, the earliest and simplest form of fire detection structure, built into a living tree.

#### Historic Contexts/ Background

The date of construction for this lookout tree, like other lookout trees, is currently unknown. The 1937 brass cap marker is the only one found in association with a lookout tree on the Kaibab National Forest, and it does indicate that the tree was in use at that time. The marker indicates that this tree was an integral part of the Kaibab National Forest fire planning system. The "Fracas Ridge Tree Lookout" appears in the Kaibab National Forest "Fire Control Visible Area Map." The "seen area" fieldwork was conducted by "H.T. and A.G.W." on October 6, 1937, correlating with the date on the associated brass cap marker.

Fracas Lookout Tree may have been abandoned in the 1960s, as other trees on the North Kaibab Ranger District were. Aside from the brass cap marker, this was a typical lookout tree facility.

9. Major Bibliographical References	
Fire Control Visible Area Map, on file at Camp Kaibab National Forest, Williams, Arizona.  Previous documentation on file (NPS):	Clover Ranger Station fire office,    _   See continuation sheet.  Primary location of additional data:
previously listed in the National Register previously determined eligible by the National Register	State hist. preservation office Other State agency Federal agency
designated a National Historic Landmark recorded by Historic American Buildings Survey # recorded by Historic American Engineering	Local government University Other
Record #	Specify repository: Kaibab National Forest, Williams, AZ
10. Geographical Data	
Acreage of property less than one	
UTM References  A   1   2     3   8   6   4   0   0     4   0   5   7   8   0   0   B  Zone Easting Northing  C	Zone Easting Northing  Zone Easting Northing  Northing  Zone Easting Northing  See continuation sheet
Verbal Boundary Description	
The boundary of the site is a square measuring on the tree itself (see accompanying sketch map	
l_	See continuation sheet
Boundary Justification	
The boundary includes the lookout tree and its	immediate area only.
11 Form Drown and Drown	_  See continuation sheet
11. Form Prepared By	
name/title Marietta A. Davenport, and Teri A. C.	
	Forest date 5-22-90
street & number 430 South Main	telephone 602-643-7395
city or town Fredonia	state AZ zip code 86022

#### United States Department of the Interior National Park Service

## NATIONAL REGISTER OF HISTORIC PLACES CONTINUATION SHEET

riiotodinariio rage i	OTOGRAPHS Page	1
-----------------------	----------------	---

THE FOLLOWING INFORMATION IS THE SAME FOR ALL PHOTOGRAPHS ACCOMPANYING THIS NOMINATION:

- 1). Fracas Lookout Tree
- 2). Vicinity of Grand Canyon, North Rim, southwest of Jacob Lake, Kaibab Plateau, Arizona
- 3). John C. Davenport
- 4). May 1990
- 5). North Kaibab Ranger District, Kaibab National Forest, Fredonia, Arizona

#### INFORMATION FOR INDIVIDUAL PHOTOGRAPHS:

- 6). Facing southwest, tree in its recently logged setting.
- 7). #1
- 8). Facing west, base of tree showing ladder.
- 9). #2
- 10). East side of tree, detail of brass cap marker.
- 11). #3

