



Reynolds Homestead
Rock Spring Plantation
On Va. 798, 1 mi. north
of Critz, via Va. 626
Critz, Virginia

Photo by: Ralph J. Christian, AASLH
Negative at: Historic Sites Survey
November 1976

Photo No. 1
View: Front (north) facade and
detached kitchen.



REYNOLDS HOMESTEAD

Photo credit: AASLH

Reynolds Homestead
Rock Spring Plantation

On Va. 798, 1 mi. north
of Critz via Va. 626

Critz, Virginia

Photo by: Ralph J. Christian, AASLH

Negative at: Historic Sites Survey

November 1976

Photo No. 2

View: Portions of ice house and milk
house, rear of kitchen, and
portion of rear (south) facade
of house.



REYNOLDS HOMESTEAD

Photo credit: AASLH

Reynolds Homestead
Rock Spring Plantation
On Va. 798, 1 mi. north
of Critz via Va. 626
Critz, Virginia

Photo by: Ralph J. Christian, AASLH
Negative at: Historic Sites Survey
November 1976

Photo No. 3

View: East side of Reynolds bedroom
with Chinese Chippendale
Stairway leading to upper story



REYNOLDS HOMESTEAD

Photo credit: AASLH

Reynolds Homestead
Rock Spring Plantation
On Va. 798, 1 mi. north
of Critz via 626
Critz, Virginia

Photo by: Ralph J. Christian, AASLH
Negative at: Historic Sites Survey
November 1976

Photo No. 4
View: West wall of Reynolds bedroom
showing fireplace and
furnishings.