

Ray Krause, Dept. of Arts-Photo Sect. Frankfort, KY.
April 1982

Photo 1 MAY 28 1982

View: House as seen from Zaring Road (from the west).



Ray Krause, Dept. of Arts-Photo Sect. Frankfort, Ky. April 1982

MAY 28 1982 Photo 2

View looking northeast.



Ray Krause, Dept. of Arts-Photo Sect. Frankfort, Ky. April 1982

Photo 3

MAY 28 1982

View looking southeast.



Ray Krause, Dept.of Arts-Photo Sect. Frankfort, Ky. April 1982

Photo 4

MAY 28 1982

View looking southeast



Ray Krause, Dept.of Arts-Photo Sect. Frankfort, Ky. April 1982

Photo 5 MAY 28 1982 View looking east.




July 1980 MAY 28 1982 Photo 7. View of main (west) facade.



Ray Krause, Dept.of Arts-Photo Sect. Frankfort, Kentucky April 1982

Photo 6 MAY 28 1982

Front (west) elevation



July 1980 MAY 28 1982
Photo 8.
View of portico from northwest.



July 1980 MAY 28 1982

Photo 9.
Betailo of anthemion cresting on




Ray Krause, Dept.of Arts-Photo Sect. Frankfort, Kentucky April 1982

Photo 10

MAY 28 1982

View of side and rear of main house, looking northwest.



Undulata
Shelby County, Kentucky
Charlotte Schneider
July 1980
Kentucky Heritage Commission

Frankfort Kentucky

July 1980

MAY 28 1982

Photo 11.
View of north porch taken from northwest.



Photo 12. MAY 28 1982 Leaded glass casement windows in east wall of northeast parlor.



July 1980 MAY 28 1982
Photo 13.
Mantel in southwest parlor.



Undulata Shelby County, Kentucky Charlotte Schneider Kentucky Heritage Commission Frankfort, Kentucky July 1980 MAY 28 1982 Photo 14. Subterranean smokehouse with stepped parapet facade (A) taken

from northeast.



Photo 15.
Round brick icehouse (B) taken from north.

July 1980



Ray Krause, Dept. of Arts-Photo Sect. Frankfort, Ky. April 1982

Photo 16 MAY 28 1982

View of outbuilding (G), looking southeast.



Photo 17

Ray Krause, Dept.of Arts-Photo Sect. Frankfort, Ky. April 1982

MAY 28 1982

View of outbuildings (left to right G, F, E, D, C), looking southeast.



Photo 18
Original frame farm office (G),taken from southwest.




Undulata Shelby County, Kentucky Charlotte Schneider

Kentucky Heritage Commission Frankfort, Kentucky MAY 28 1982

July 1980 Photo 19. Frame horse barns (E) taken south-

west.



Undulata Shelby County, Kentucky Charlotte Schneider Kentucky Heritage Commission Frankfort, Kentucky July 1980 MAY 28 1982 Photo 20. Concrete block office (D) taken


from southwest.



Ray Krause, Dept. of Arts-Photo Sect. Frankfort, Ky.
April 1982 MAY 2 9 1982

Photo 21

View of outbuilding (C), looking east.



Ray Krause, Dept. of Arts-Photo Sect. Frankfort, Ky.
April 1982

MAY 2 3 1982

Photo 22

View of outbuilding (H), looking northeast.



Ray Krause, Dept. of Arts-Photo Sect. Frankfort, Ky.
April 1982

Photo 23

View of farm road, looking west.



Ray Krause, Dept. of Arts-Photo Sect. Frankfort, Ky. April 1982

MAY 2 3 1982

Photo 24

View of outbuilding (K), looking northeast.



IIndulata Shelby County, Kentucky Charlotte Schneider Kentucky Heritage Commission Frnakfort, Kentucky July 1980 Photo 25. Concrete block dairy (K, now kenne): taken from southwest.



Undulata
Shelby County, Kentucky
Charlotte Schneider
Kentucky Heritage Commission
Frankfort, Kentucky

July 1980 MAY 28 1382 Photo 26. 1 1/2-story frame barn (L) taken from east.



Undulata
Shelby County, Kentucky
Charlotte Schneider
Kentucky Heritage Commission
Frankfort, Kentucky

July 1980 MAY 28 1982 Photo 27.

One-story frame cottage (N) taken from northeast.



IIndulata Shelby County, Kentucky Charlotte Schneider Kentucky Heritage Commission Frankfort, Kentucky MAY 28 1562

Photo 28.
Two-story frame T-plan (M) taken from northwest.