

2000-01-01



NEWSON'S MILL
NASHVILLE, TN.
PHOTO NO. 1

WEST SIDE OF MILL
DAVIDSON CO., TENN



NEWSOM'S MILL

NASHVILLE, TN.

PHOTO NO. 2

DAVIDSON Co., TENN.

FACING NORTH; VIEW OF BROKEN DAM + FOUNDATIONS



NEWSOM'S MILL
NASHVILLE, TN.

PHOTO NO. 3

SOUTH SIDE OF MILL, SHOWING ENTRANCE + LOADING/UNLOADING DOCK
DAVIDSON Co., TENN



NEWSOM'S MILL
NASHVILLE, TN.

PHOTO NO. 4

OPENING IN PORCH OF LOADING/UNLOADING DOCK (SOUTH SIDE)

DAVIDSON CO., TENN



NEWSOM'S MILL
NASHVILLE, TN.

PHOTO NO. 5
DAVIDSON CO., TENN.

TAKEN FROM ENTRANCE IN SOUTH WALL; SHOWS CONCRETE
FOUNDATION, WITH ATTACHING BOLTS, WHICH SUPPORTED MILL
EQUIPMENT (NORTH WALL IN BACKGROUND)



NEWSOM'S MILL
NASHVILLE, TN.

PHOTO NO. 6

DAVIDSON CO., TENN.

JOINING OF WEST AND NORTH WALLS, SHOWING ROOF-LINE AND
ONLY REMAINING PIECE OF MILL MACHINERY