



Photograph #1
Main Street Bridge, Stamford, CT
Northwest View of North Trusses
Steven Bedford, August 1986
Negative on file at Connecticut Historical Commission

APR 24 1987



Photograph #2

Main Street Bridge, Stamford, CT

Northeast End Assembly, Northwest View

Steven Bedford, August 1986

Negative on file at Connecticut Historical Commission




Photograph #3

Main Street Bridge, Stamford, CT

Western edge of bridge, Southwest View

Steven Bedford, August 1986

Negative on file at Connecticut Historical Commission



Photograph #4

Main Street Bridge, Stamford, CT

Detail of pin-hanger connection

Steven Bedford, August 1986

Negative on file at Connecticut Historical Commission



Photograph #5

Main Street Bridge, Stamford, CT

Southwest View of piers and floor beams

Steven Bedford, August 1986

Negative on file at Connecticut Historical Commission



Photograph #6

Main Street Bridge, Stamford, CT

Southwest View of South Trusses

Steven Bedford, August 1986

Negative on file at Connecticut Historical Commission



Photograph #7

Main Street Bridge, Stamford, CT

Southwest View

Steven Bedford, August 1986

Negative on file at Connecticut Historical Commission



Photograph #8
Main Street Bridge, Stamford, CT
East View
Steven Bedford, August 1986
Negative on file at Connecticut Historical Commission

APR 24 1987