

Main Avenue Historic, District Durango, Colorado Ja Delata Co. Photographer: Marjorie Wells Date of Photograph: 1980 Negatives in possession of Colorado Preservation Office View: This streetscape looks north from a point very near the southern boundary Photographer looking north

JUN 3 0 1980



Main Avenue Historic District to plate co Durango, Colorado Photographer: Marjorie Wells Date of Photograph: 1980 Negatives in possession of Colorado Preservation Office JUN 3 0 1980 View: South Boundary Photographer looking south The boundary moves from left to right across the middle of the photograph. All structures

shown are outside the district



Main Avenue Historic District
Durango, Colorado fa plata co. #3 Photographer: Marjorie Wells Date of Photograph: 1980 Negatives in possession of Colorad**JUN 3 0 1980** Preservation Office View: Southwest corner of the Historic Dist. Photographer looking westerly Other: This corner of the district, hidden beneath the snow (center) shows the place where the district and the Durango-Silverton Narrow Gauge Railroad Historic District meet.



Main Avenue Historic District Durango, Colorado Ja Plata Co. Photographer: Marjorie Wells Date of Photograph: 1980 Negatives in possession of Colorado Preservation Office View: West boundary of the District Photographer looking north Other: At left is the Durango-Silverton Narrow Gauge Railroad Historic District; at right is the Main Avenue Historic District



Main Avenue Historic District
Durango. Colorado In Plata Co Photographer: Marjorie Wells Date of Photograph: 1980 Negatives in possession of Colorado Preservation Office View: Northwest boundary Photographer looking northerly This photograph shows the tracks of the Durango-Silverton Narrow Gauge Historic District at left, and the street forming the northern boundary of the Main Avenue District in the center.



Main Avenue Historic District Photographer: Marjorie Wells
Date of Photograph: Negatives in possession of Colorado 3 0 1980 Preservation Office View: Southeast boundary of the district Photographer looking south



Main Avenue Historic District
Durango, Colorado

Main Avenue Historic District

Plata Cs. 38 Photographer: Marjorie Wells Date of Photograph: 1980 Negatives in possession of Colorado Preservation Office View: Looking north from north boundary on Main Avenue Photographer looking north



Main Avenue Historic District Durango, Colorado Ja Plata Co 131 Photographer: Marjorie Wells Date of Photograph: 1980 Negatives in possession of Colorado Preservation Office View: Looking north between 8th and 9th Street Photographer looking north JUN 3 0 1980 This alleyway forms the eastern boundary of the district. Historic structures to the


left or west.




Strater Hotel (Structure #8) Main Avenue Historic District Durango, Colorado Ta Plata Co. Photographer: Marjorie Wells Date of Photograph: 1980 Negatives in possession of Colorado JUN 3 0 1980 Preservation Office View: north facade Photographer looking south Main Avenue can be seen at the extreme left



Strater Hotel (Structure #8) Main Avenue Historic District Durango, Colorado Photographer: Marjorie Wells Date of Photograph: 1980 Negatives in possession of Colorado Preservation Office View: Main (east) facade Photographer looking westerly




Newman Building (Structure #17) Main Avenue Historic District Photographer: Marjorie Wells & Plata Co.
Date of Photographer Durango, Colorado Date of Photograph: 1980 Negatives in possession of Colorado Preservation Office View: Main (east) facade Photographer looking westerly



Newman Building (Structure #17) Main Avenue Historic District Photographer: Marjorie Wells La Plata Co. Date of Photograph: 1980 Negatives in possession of Colorado JUN 3 0 1980 Preservation Office View: South facade Photographer looking north



Manny's Town House (Structure #75) Main Avenue Historic District Durango, Colorado Photographer: Marjorie Wells Date of Photograph: 1980 Negatives in possession of Colorado Preservation Office View: North (left) and West (main right) facades Photographer looking southeasterly across Main Avenue from 10th Street



Old Post Office Building (Structure #84) Main Avenue Historic District7 Durango, Colorado Photographer: Marjorie Wells Date of Photograph: 1980 Negatives in possession of Colorado Preservation Office View: West (main) facade Photographer looking east




Gallerie Maguerite (Structure #92) Main Avenue Historic District Durango, Colorado Photographer: Manjonie Wells Date of Photograph: 1980 Negatives in possession of Colorado Preservation Office JUN 3 0 1980 View: North (main) facade Photographer looking south



Main Avenue Historic District


Durango, Colorado Photographer: Marjorie Wells Date of Photograph: 1980 Negatives in possession of Colorado Preservation Office JUN 3 0 1980 View: North facade Photographer looking south from 10th Street




Central Hotel (Structure #27) Main Avenue Historic District Durango, Colorado Photographer: Marjorie Wells Date of Photograph: 1980
Negatives in possession of Colorade 3 Preservation Office View: Main (east) facade Photographer looking west



Masonic Hall (Structure #96) Main Avenue Historic District La Alata Co. Durango, Colorado Photographer: Marjorie Wells Date of Photograph: 1980 Negatives in possession of Colorado Preservation Office JUN 3 0 1980 View: Main facade



N. T. Thomson Building (Structure #45) left _ and Mr. Rosewater's (Structure #44) right Main Avenue Historic District Ja Plata Ca Photographer: Marjorie Wells Date of Photograph: 1980 Negatives in possession of Colorado Preservation Office Photographer looking west



Sportsman's Lounge (Structure #52) and Lost Pelican (Structure #53) right Main Avenue Historic District & Plate Co Durango, Colorado Photographer: Marjorie Wells Date of Photograph: 1980 Negatives in possession of Colorado Preservation Office View: Main facades Photographer looking east


Purgatory Sports (Structure #41) right and 3/ Crazy Horse Hair (Structure #42) left Main Avenue Historic District La Plata Co. Photographer: Marjorie Wells Date of Photograph: 1980 Negatives in possession of Colorado Preservation Office View: Main facades Photographer looking west



First National Bank (Structure #20) Main Avenue Historic District J Durango, Colorado Photographer: Marjorie Wells Date of Photograph 1980 Negatives in possession of Colorado Preservation Office View: Main (east) facade Photographer looking west JUN 3 0 1980




Burns Bank (Structure #66) Main Avenue Historic District Durango, Colorado Photographer: Marjorie Wells Date of Photograph: 1980 Negatives in possession of Colorado Preservation Office JUN 3 0 1980 View: West (Main) facade Photographer looking east



Turn-of-the Century (Structure, #50) Main Avenue Historic District fa Plata Co. Photographer: Marjorie Wells Date of Photograph: 1980 Negatives in possession of Colorado Preservation Office View: West (main) facade JUN 3 0 1980 Photographer looking east




N. T. Thomson Building (Structure #45) left Mr. Rosenwater's (Structure #44) center La Plata #25/3/ Durango, Colorado Photographer: Marjorie Wells Date of Photograph: 1980 Negatives in possession of Colorado Preservation Office View: Main (West) facades JUN 3 0 1980 Photographer looking east



Haffey's and Concepts in Clothing Structure #58), left and New York Bakery (Structure #57) right Main Avenue Historic District Ja Alata Co.31

Durango, Colorado Photographer: Marjorie Wells Date of Photograph: 1980 Negatives in possession of Colorado Preservation Office JUN 3 0 1980 View: East facades Photographer looking west



Phillips 66 Station (Structure #47) Main Avenue Historic District Photographer: Marjorie Wells La Plata Co. Date of Photograph: 1980 Negatives in possession of Colorado Preservation Office JUN 3 0 1980 View: North and west facades Photographer looking southerly



Burns Bank (Structure #66)
Main Avenue Historic District La Pleta ca, Durango, Colorado Photographer: Marjorie Wells Date of Photograph: 1980 Negatives in possession of Colorado Preservation Office View: South (side) facade _NN 3 0 1980 Photographer looking northwesterly This photograph shows ten historic portions of the bank at left and the new section at right.



Cat & Fiddle, and Seismos (Structure #49) (Main Avenue Historic District) Durango, Colorado Ja Alata Catt 29/2 Photographer: Marjorie Wells Date of Photograph: 1980 Negatives in possession of Colorado Preservation Office View: West (main) facades Photographer looking east JUN 3 0 1980 Other: intrusions



Treasure Tunnel (Structure #5), Gold #30/3/ Slipper (Structure #6), and Strater Arcade (Structure #7), left to right Main Avenue Historic District |
Durango, Colorado La Plata Co. Photographer: Marjorie Wells Date of Photograph: 1980 Negatives in possession of Colorado Preservation Office View: East (main) facades 3 0 1980 Photographer looking west



Stone House Bakery (Structure #104) Main Avenue Historic District) for Alata Ca. Photographer: Marjorie Wells Date of Photograph: 1980 Negatives in possession of Colorado Preservation Office View: Main (north) and west facades Photographer looking southwesterly

