

FORM 10-301 A

UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

PROPERTY PHOTOGRAPH FORM

(Type all entries - attach to or en close with photograph)

(1) pe as	· Ontrios divident to the	- 10 1-1/
1. NAME		
COMMON	Cedar Cluse,	NUMERIC CODE (Assigned by NPS)
Bradley House	John W. Bradley House	NOV 5 1974
2. LOCATION		
STATE	COUNTY	томи
Kentucky	Scott	Georgetown
STREET AND NUMBER		
Paynes Depot Pike (U.S.	62) 3/4 mile west of hig	hway on Cane Run
3. PHOTO REFERENCE		
PHOTO CREDIT	DATE	Rt.4, Lexington Pike
Ann B. Bevins	1971	Georgetown, Kentucky
4. IDENTIFICATION		1617
Photo showing view	of house taken from east	RECEIVED AUG. 1 2 1974 NATIONAL REGISTE



FORM 10-301 A (6/72)

UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES PROPERTY PHOTOGRAPH FORM

(Type all entries - attach to or en close with photograph)			
1. NAME		NATIONA	
COMMON	AND/OR HISTORIC	NUMERIC CODE (Assistante by NPS)	
Bradley House	Cedar Cluse, John W. Br	adley	
2. LOCATION	House	(10)	
STATE	COUNTY	TOWN	
Kentucky STREET AND NUMBER	Scott	Georgetown	
Paynes Depot Pike (U. S	6. 62) 3/4 mile west of h	ighway on Cane Run	
3. PHOTO REFERENCE			

PHOTO CREDIT DATE NEGATIVE FILED AT Rt. 4, Lexington Pike Ann Bevins July, 1974 Georgetown, Kentucky

4. IDENTIFICATION

DESCRIBE VIEW, DIRECTION, ETC.

Photo showing mantel on interior wall in south end of structure



FORM 10-301 A

UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES PROPERTY PHOTOGRAPH FORM

(Type all entries - attach to or enclose with photograph)

	ype all entitles - attach to or en orose	
1. NAME		AUG 1 2 1000 10
COMMON	AND/OR HISTORIC	NUMERIC CODE (Assigned by NPS)
		MOVONA1974
Bradley House	Cedar Cluse, John W.	Bradley REGISTER
2. LOCATION	House	
STATE	COUNTY	TOWN NWOT
Kentucky	Scott	Georgetown
STREET AND NUMBER		
Paynes Depot Pike (U.	S. 62) $3/4$ mile west of his	ghway on Cane Run
3. PHOTO REFERENCE		
PHOTO CREDIT	DATE	Rt. 4. Lexington Pike

4. IDENTIFICATION

Ann Bevins

DESCRIBE VIEW, DIRECTION, ETC.

Photo showing chair railing and window detail of attic in north end of structure.

July, 1974

Georgetown, Kentucky

