



JOHN C. VANSANT HOUSE (N-218)

NEWARK (VICINITY), DELAWARE

PHOTOGRAPHER JUDITH HOFER

MAY 1998

LOCATION OF NEGATIVE: DELAWARE BUREAU OF ARCHAEOLOGY

& HISTORIC PRESERVATION IS THE GREEN,

DOVER, DELAWARE

FRONT FACADE FROM SOUTHWEST

1998



JOHN C. VANSANT HOUSE (N-218)

NEWARK (VICINITY), DELAWARE

PHOTOGRAPHER: JULIA R. HOFER

MAY 1988

LOCATION OF NEGATIVE: DELAWARE BUREAU OF ARCHAEOLOGY
& HISTORIC PRESERVATION, 15 THE GREEN,
DOVER, DELAWARE

ADDITION, FRONT FACADE FROM SOUTHEAST

2 of 12



JOHN C. VANSANT HOUSE (N-218)

NEWARK (VINTAGE), DELAWARE

PHOTOGRAPHER: JULIA R. HOFER

MAY 1988

LOCATION OF NEGATIVE: DELAWARE BUREAU OF ARCHAEOLOGY
& HISTORIC PRESERVATION, 15 THE GREEN,
DOVER, DELAWARE

SIDE & REAR PORCHES FROM NORTHWEST

Fig. 12.



JOHN C. VANSANT HOUSE (N 218)

NEWARK (VICINITY), DELAWARE

PHOTOGRAPHER: JOHN R. HOFER

MAY 1985

LOCATION OF NEGATIVE: DELAWARE BUREAU OF ARCHAEOLOGY

& HISTORIC PRESERVATION, 15 THE GREEN

DOVER, DELAWARE

REAR FACADE FROM NORTH

9 of 12



JOHN C. VANSANT HOUSE (N-218)

NEWARK (VICINITY), DELAWARE

PHOTOGRAPHER: VALERIE CESNA

October 1997


LOCATION OF NEGATIVE: DELAWARE BUREAU OF HISTORIOLOGY

& HISTORIC PRESERVATION, 15 THE GREEN,

DOVER, DELAWARE

1st Floor Hall & Staircase from southwest

5 of 12



JOHN C. VANSANT HOUSE (N-218)

NEWARK (VICINITY), DELAWARE

PHOTOGRAPHER: VALERIE CESNA

APRIL 1988

LOCATION OF NEGATIVE: DELAWARE BUREAU OF ARCHAEOLOGY
& HISTORIC PRESERVATION, 15 THE GREEN,
DOVER, DELAWARE

1st Floor. Southwest Interior, FIREPLACE WALL FROM EAST

6 of 12



JOHN C. VANSANT HOUSE (W-218)

NEWARK (VICINITY), DELAWARE

PHOTOGRAPHER: VALERIE CESNA

OCTOBER 1987

LOCATION OF NEGATIVE: DELAWARE BUREAU OF ARCHAEOLOGY
& HISTORICAL PRESERVATION, 15 THE GREEN
DOVER, DELAWARE

INTERIOR OF FRONT DOOR FROM NORTH

7 of 12



JOHN C. VANSANT HOUSE (A-218)

NEWARK (VICINITY), DELAWARE

PHOTOGRAPHER: CURT R. HOFER

MAR 1982

LOCATION OF NEGATIVE: DELAWARE BUREAU OF ARCHAEOLOGY
& HISTORIC PRESERVATION

15 THE GREEN

DOVER, DELAWARE

AGRICULTURAL OUTBUILDINGS FROM NORTHWEST

8 of 12



JOHN C. VANSANT HOUSE (N-218)

NEWARK (VICINITY), DELAWARE

PHOTOGRAPHER: JULIA R. HOFER

MAY 1988

LOCATION OF NEGATIVE:

DELAWARE BUREAU OF ARCHAEOLOGY

& HISTORIC PRESERVATION

15 THE GREEN

DOVER, DELAWARE

EQUIPMENT SHED FROM SOUTH

9 of 12



JOHN C. VANSANT HOUSE (N-218)
NEWARK (VICINITY), DELAWARE

PHOTOGRAPHER: JULIA R. HOFER
MAY 1988

LOCATION OF NEGATIVE:

DELAWARE BUREAU OF ARCHAEOLOGY
& HISTORIC PRESERVATION
15 THE GREEN
DOVER, DELAWARE

BARN FROM SOUTH

10 of 12



John C. VAUGHAN House (N-218)

NEWARK (VICINITY), DELAWARE

PHOTOGRAPHER: JUDITH R. HOOPER

MAY 1988

LOCATION OF NEGATIVE:

DELAWARE BUREAU OF ARCHAEOLOGY

& HISTORIC PRESERVATION

15 THE GREEN

DOVER, DELAWARE

BARN FROM SOUTHWEST

11 of 12



JOHN C. VANSANT HOUSE (N-218)

NEWARK (VICINITY), DELAWARE

PHOTOGRAPHER: JULIA R. HOFER

MAY 1988

LOCATION OF NEGATIVE:

DELAWARE BUREAU OF ARCHAEOLOGY
& HISTORIC PRESERVATION

15 THE GREEN

DOVER, DELAWARE

CORN CRIB FROM NORTH

12 of 12