



Cathedral

1. Trinity Episcopal ~~Church~~
2. Miami, Florida
3. Ivan A. Rodriguez
4. 1979
5. Dade County Historic Survey, Miami,
Florida
6. West (front) elevation
7. Photo No. 1/6

Dade CO

AUG 4 1980

OCT 10 1980



Cathedral

1. Trinity Episcopal ~~Church~~
2. Miami, Florida
3. Ivan A. Rodriguez
4. 1979
5. Dade County Historic Survey, Miami
Florida
6. North (side) and west (front) elevations
7. Photo No. 2/6

AUG 4 1980

OCT 10 1980



Cathedral

1. Trinity Episcopal ~~Church~~
2. Miami, Florida
3. Ivan A. Rodriguez
4. 1979
5. Dade County Historic Survey, Miami,
Florida
6. South (side) and west (front) elevations
7. Photo No. 3/6

OCT 10 1980

AUG 4 1980



NO
PARKING
ANY
TIME

ONE WAY

Cathedral

1. Trinity Episcopal ~~Church~~
2. Miami, Florida
3. Ivan A. Rodriguez
4. 1979
5. Dade County Historic Survey, Miami,
Florida
6. North (side) and east (apse) elevations
7. Photo No. 4/6

AUG 4 1980

OCT 10 1980



Cathedral

1. Trinity Episcopal ~~Church~~
2. Miami, Florida
3. Ivan A. Rodriguez
4. 1979
5. Dade County Historic Survey, Miami,
Florida
6. Interior view towards Narthex
7. Photo No. 5/6

AUG 4 1980

OCT 10 1980



Cathedral

1. Trinity Episcopal ~~Church~~
2. Miami, Florida
3. Ivan A. Rodriguez
4. 1979
5. Dade County Historic Survey, Miami,
Florida
6. Interior view towards Altar
7. Photo No. 6/6

OCT 10 1980

AUG 4 1980