

1 Of 16 Presentation drawing with watercolor wash, "Design Plan for Garden Treatment," prepared by the Salem landscape architecture firm of

Lord and Schryver and dated "Fall of 1931." The drawing was mounted and framed for use as a fireplace screen by the original occupants.

Copy negative in possession of current occupants: Mr. and Mrs. Robert Gormsen 460 Leffelle Street South Salem, OR 97302



George Strozut Photo, 1982 Negative: David C. Duniway 1365 John Street S. Salem, QR 97302

2 of 16 General view of property from Leffelle Street, looking south.



George Strozut Photo, 1982 Negative: David C. Duniway 1365 John Street S. Salem, OR 97302

3 of 16 North(front) elevation from driveway.



George Strozut Photo, 1982 Negative: David C. Duniway 1365 John Street S. Salem, OR 97302

4 of 16 South(garden) elevation from flower garden.



## George Strozut Photo, 1982 Negative: David C. Duniway 1365 John Street S. Salem, QR 97302

5 of 16 South elevation, looking easterly along lower terrace.



## George Strozut Photo, 1982 Negative: David C. Duniway 1365 John Street S. Salem, QR 97302

## 6 of 16

South elevation, looking westerly along lower terrace toward arbor termination.



George Strozut Photo, 1982 Negative: David C. Duniway 1365 John Street S. Salem, OR 97302

7 of 16 South elevation, looking westerly along upper garden terrace toward trellis marking entrance to small

"reserve garden."



George Strozut Photo, 1982 Negative: David C. Duniway 1365 John Street S. Salem, OR 97302

8 of 16 East end elevation showing small porch in southeast corner giving access to the study.



George Strozut Photo, 1982 Negative: David C. Duniway 1365 John Street S. Salem, OR 97302

9 of 16 Entry stairhall, looking southwesterly, showing raking section of stair railing.



George Strozut Photo, 1982 Negative: David. C. Duniway 1365 John Street S. Salem, OR 97302

10 of 16 Dining room, looking southwesterly. North-south axis of garden layout is centered on the dining room window.



George Strozut Photo, 1982 Negative: David C. Duniway 1365 John Street S. Salem, OR 97302

11 of 16 Dining room, looking easterly into living room. Note ogee-arched doorway.



George Strozut Photo, 1982 Negative: David C. Duniway 1365 John Street S. Salem, OR 97302

12 of 16 Living room, looking westerly into stairhall and dining room. Heavilymullioned windows with leaded panes are typical.



George Strozut Photo, 1982 Negative: David C. Duniway 1365 John Street S. Salem, OR 97302

13 Of 16 Living room, looking southeasterly. Chimneypiece is distinguished by Tudor-arched fireplace opening and by linen fold paneling.



George Strozut Photo, 1982 Negative: David C. Duniway 1365 John Street S. Salem, OR 97302

14 Of 16 Living room, looking east into study. Note ogee-arched doorway.



George Strozut Photo, 1982 Negative: David C. Duniway 1365 John Street S. Salem, RO 97302

15 of 16 Study, looking northwesterly, traditionally finished with dark paneling, mullioned windows with

leaded panes, heraldic motif in colored glass.



George Strozut Photo, 1982 Negative: David C. Duniway 1365 John Street S. Salem, OR 97320

16 of 16 Study, looking southeasterly. Note coved cornice. Doorway gives access to small porch at secluded corner of garden.