

D.S.Plummer, 9/82 Photograph 1

Hartford, Connecticut

Front and Southeast side of house Negative on file at Ct. Hist. Comm.



Simon Tiffany House Salem, Connecticut D.S.Plummer, 9/82


D.S.Plummer, 9/82
Photograph 2
Rear of house
Negative on file at Ct. Hist. Comm.



Simon Tiffany House Salem, Connecticut D.S. Plummer, 9/82 Photograph 3 Detail of crown molding above windows

Hartford, Connecticut

Negative on file at Ct. Hist. Comm.



Simon Tiffany House Salem, Connecticut D.S.Piummer, 9/82 Photograph 4 Northeast side of house Negative on file at Ct. Hist. Comm. Hartford, Connecticut



Simon Tiffany House Salem, Connecticut Historic photograph, 1940 Photograph 5 Rear of house Copy negative on file at Ct. Hist. Comm. Hartford, Connecticut



D.S.Plummer, 9/82 Photograph 6 Front Stairway Negative on file at Ct. Hist. Comm.



Hartford, Connecticut

Detail, Staircase molding

Negative on file at Ct. Hist. Comm.

D.S.Plummer, 9/82 Photograph 7



Simon Tiffany House Salem, Connecticut D.S.Plummer

Negative on file at Ct. Hist. Comm.

Photograph 8 Interior of parlor



D.S.Plummer, 9/82 Photograph 9 Parlor fireplace and mantelpiece Negative on file at Ct. Hist. Comm.



D.S.Plummer, 9/82 Photograph 10 Inside shutter, parlor Negative on file at Conn. Hist. Comm. Hartford, Connecticut



Simon Tiffany House


Salem, Connecticut

D.S.Plummer Photograph 11

Hartford, Connecticut

Negative on file at Ct. Hist. Comm.

Kitchen Interior



Negative on file at Ct. Hist. Comm.

D.S.Plummer, 9/82 Photograph 12 Garage



Negative on file at Ct. Hist. Comm.

D.S.Piummer, 9/82 Photograph 13 Outbuilding (former barn)



Simon Tiffany House Salem, Connecticut Historic Photograph, circa 1924 Photograph 14 Front and southeast side of house Copy negative on file at Ct. Hist. Comm. Hartford, Connecticut