



S THRU SUN 2PM
MAY
659 2211

Va
FREE INST
PLASTER

HARTCO
BUILDING
MATERIALS
CO. INC.
1000
1000

WALKER
ARTISTS
CORP.

ARTISTS
CORP.

ARTISTS
CORP.

1329-1335 119TH ST WHITING, IN.

HOOSIER THEATER BUILDING, WHITING, IN.

SIMSTAD / 310-56-7887

SOUTH VIEW OF BUILDING LOOKING NORTH WEST

The Hoosier Theater Building - Whiting, Indiana.
Photographed by Thomas Simstad, April 1986.
Negative located with building owner.
#1 - North-west view, showing south facade



1110 N. ...
1110 N. ...

HAR BLOCK
YOU'LL FIND AS
MUCH TO
BUY OF HONDA
AS YOU WANT
853-7100

TAMPA

1329-1335. 119TH ST. WHITING, IN.

HOOSIER THEATER BUILDING, WHITING, IN

SIMSTAD/310-56-7887

SOUTH + WEST VIEW OF BUILDING LOOKING NORTH-EAST

The Hoosier Theater Building - Whiting, Indiana.
Photographed by Thomas Simstad, April 1986.
Negative located with building owner.
#2 - North-east view



1333 - 119TH ST, WHITING IN
HOOSIER THEATER, WHITING. IN
SIMSTAD / 310-56-7887

INTERIOR VIEW OF THEATER LOOKING WEST
FROM THE BALCONY:

The Hoosier Theater Building - Whiting, Indiana.
Photographed by Thomas Simstad, April 1986.
Negative located with building owner.
#3 - West view, from balcony - showing theater's
interior



M-Dater Waste

663 3914

Va
FINE WEL
PLASTER

The Hoosier Theater Building - Whiting, Indiana.

Photographed by Thomas Simstad, April 1986.

Negative located with building owner.

#4 - Northwest view depicting ornate,

multicolored terra cotta, marquee, theater

entrance and store fronts.



The Hoosier Theater Building - Whiting, Indiana.

Photographed by Thomas Simstad, April 1986.

Negative located with building owner.

#5 - Northeast view depicting ornate terra cotta, quality face brick and the distinguishable separation between structures.



TURNAK
ROOFING
800-894-4002

The Hoosier Theater Building - Whiting, Indiana.
Photographed by Thomas Simstad, April 1986.
Negative located with building owner.
#6 - Northeast view depicting ornate terra cotta
in greater detail.



The Hoosier Theater Building - Whiting, Indiana.
Photographed by Thomas Simstad, April 1986.
Negative located with building owner.
#7 - Southeast view depicting raised roof area
above stage that allows for the 'flying' screen
and other rigging.



The Hoosier Theater Building - Whiting, Indiana.
Photographed by Thomas Simstad, April 1986.
Negative located with building owner.
#8 - North view, close-up of ornate and detailed
terra cotta above marquee.



The Hoosier Theater Building - Whiting, Indiana.

Photographed by Thomas Simstad, April 1986.

Negative located with building owner.

#9 - North view, showing the exquisite,
hand-crafted 'dancing lady' above marquee.



The Hoosier Theater Building - Whiting, Indiana.
Photographed by Thomas Simstad, April 1986.
Negative located with building owner.
#10 - North view, showing detailed terra cotta
work including 'lady's mask' and rosette trim
above marquee.



The Hoosier Theater Building - Whiting, Indiana.

Photographed by Thomas Simstad, April 1986.

Negative located with building owner.


#11 - North-east view from lobby of brass and
crystal chandelier.




The Hoosier Theater Building - Whiting, Indiana.
Photographed by Thomas Simstad, April 1986.
Negative located with building owner.
#12 - North view of theater's foyer showing
brass and crystal chandeliers and the wood
framed, leaded glass windows.



The Hoosier Theater Building - Whiting, Indiana.
Photographed by Thomas Simstad, April 1986.
Negative located with building owner.
#13 - South-east view showing detailed plaster
work on walls, ceiling and the cornice trim.
Also note large brass chandelier.



The Hoosier Theater Building - Whiting, Indiana.
Photographed by Thomas Simstad, April 1986.
Negative located with building owner.
#14 - South-west view showing detailed plaster
work around stage, ornate wood grill work and
plaster columns.



The Hoosier Theater Building - Whiting, Indiana.
Photographed by Thomas Simstad, April 1986.
Negative located with building owner.
#15 - South-west view showing close-up detail of
plaster work around stage, ornate wood grill
work and plaster columns.



The Hoosier Theater Building - Whiting, Indiana.
Photographed by Thomas Simstad, April 1986.
Negative located with building owner.
#16 - South-east view of hallway, 'ice box'
access door for delivery of ice, wainscoating,
and hard wood floor.



The Hoosier Theater Building - Whiting, Indiana.
Photographed by Thomas Simstad, April 1986.
Negative located with building owner.
#17 - North view of typical apartment unit
showing cornice work, wood double hung windows
and French doors separating living room from
bath/closet area.

17 of 18



The Hoosier Theater Building - Whiting, Indiana.
Photographed by Thomas Simstad, April 1986.
Negative located with building owner.
#18 - South-west view of typical apartment
showing cornice work, wood double hung windows
and base board.

18 of 18