

HNF # 79.05

Looking northwesterly, the easterly facade of the John Dicks House.


Photo 1 of 6



HNF # 79.26

Looking southwesterly, the entry hallway of the John Dicks House.

Photo 2 of 6



HNF# 79.34

View of the ceiling dome taken from the first story of the entry hallway.

Photo 3 of 6



HNF#79.32

Looking southwesterly, the dining room ceiling of the John Dicks House.

Photo 4 of 6



HNF# 86.13

Looking northwesterly, a ca. 1893 view of the southernmost first-story room showing elaborate mantel piece, niche beside mantel piece, wainscoting, and cornice.

Photo 5 of 6



Looking southwesterly, a ca. 1893 view of the hallway ceiling dome with moon and constellations that also shows secondstory, balcony hallway.

Photo 6 of 6