



1. The Michel Prudhomme Home
2. Opelousas, La. *St. Landry Parish*
3. C. Kenneth Deshotel
4. January 1976
5. P. O. Drawer 1668, Opelousas, La.
6. View of front (west side)
7. No. 1 *17*

DOE MAY 24 1977 APR 5 1977



- #
1. The Michel Prudhomme Home
 2. Opelousas, La. *St. Landry Parish*
 3. C. Kenneth Deshotel
 4. January 1976
 5. P. O. Drawer 1668, Opelousas, La.
 6. View of rear (east side)
 7. No. 2 of 17

APR 5 1977

MAY 24 1977 *Joe*



1. The Michel Prudhomme Home
2. Opelousas, La. *St. Landry Parish*
3. C. Kenneth Deshotel
4. January 1976
5. P. O. Drawer 1668, Opelousas, La.
6. View of north side
7. No. 3 *417*

APR 5 1977

MAY 24 1977 *Doc-*



1. The Michel Prudhomme Home
2. Opelousas, La. *St. Landry Parish*
3. C. Kenneth Deshotel
4. January 1976
5. P. O. Drawer 1668, Opelousas, La.
6. View of south side
7. No. 4 *of 17*

APR 5 1977

MAY 24 1977 *Doc-*



1. The Michel Prudhomme Home
2. Opelousas, La.
3. Rod Mikinski *St. Landry Parish*
4. February 1976
5. Opelousas Daily World
6. Pigeonnier - North and east sides
North side with door - east side
with window
7. No. 5 *of 17*

MAY 24 1977 Doc-

APR 5 1977



1. The Michel Prudhomme Home
2. Opelousas, La.
3. Rod Mikinski *St. Landry Parish*
4. February 1976
5. Opelousas Daily World
6. Corncrib - east and south sides
South side with door
7. No. 6 of 17

APR 5 1977

Doc MAY 24 1977



1. The Michel Prudhomme Home
2. Opelousas, La.
3. Daily World Photographer
4. July 1976
5. Kenneth Deshotel, Opelousas, La.
6. Pigeonnier, looking southwest, about 60 feet from the right front corner of house. Originally was an identical pigeonnier to left front of house, but no longer remains. Interior has same type of beaded beams as
7. No. 78 MAY 24 1977 Doc in house.

APR 5 1977

St. Landry Parish



1. The Michel Prudhomme Home
2. Opelousas, La.
3. Daily World Photographer
4. July 1976
5. Kenneth Deshotel, Opelousas, La. *St Landry Parish*
6. Corncrib to the southeast of house, about 30 feet away. Originally was on other side of house but had to be moved because wasn't within present property boundaries. Has same pegged construction as found in framing of house roof.
7. No. 8 *4/17*

APR 5 1977

MAY 24 1977 *DOG*



1. The Michel Prudhomme Home
2. Opelousas, La. *St Landry Parish*
3. Daily World Photographer
4. July 1976
5. Kenneth Deshotel, Opelousas, La.
6. Roof framing timbers, showing hewn cypress
and pegged construction
7. No. 9 *2/17*

MAY 24 1977 *Doc-*

APR 5 1977




1. The Michel Prudhomme Home
2. Opelousas, La. *St. Landry Parish*
3. Daily World Photographer
4. July 1976
5. Kenneth Deshotel, Opelousas, La.
6. Briquette-entre-poteaux, now uncovered, on south end of front gallery, second floor
7. No. 10 *at 17*

APR 5 1977

MAY 24 1977 Doc-

RECORDS OF THE NATIONAL ARCHIVES



1. Michel Prudhomme Home
2. Opelousas, La. *St. Landry Parish*
3. Daily World Photographer
4. July 1976 **APR 5 1977**
5. Kenneth Deshotel, Opelousas, La.
6. Exterior door of the southwest corner room, upstairs, opening onto the gallery. Shows the scored stucco facade, the briquette-entre-poteaux construction, some of which is now exposed, and the batten
7. No. *11* **MAY 24 1977 Doc** shutters.

PROPERTY OF THE NATIONAL ARCHIVES



1. Michel Prudhomme Home
2. Opelousas, La.
3. Daily World Photographer **APR 5 1977**
4. July 1976 *St Landry Parish*
5. Kenneth Deshotel, Opelousas, La.
6. Interior of front door on first floor at northwest corner of house. May be an original door. Panelling shown is used in only two rooms - this one which recently served as a bedroom and the adjoining room which is a bathroom. **MAY 24 1977**
7. No. 12 *217*



1. Michel Prudhomme Home
2. Opelousas, La.
3. Daily World Photographer **APR 5 1977**
4. July 1976 *St. Landry Parish*
5. Kenneth Dëshotel, Opelousas, La.
6. Cypress beaded beams and ceiling boards in second floor center room at front of house (west). Originally was living room. Original moulding in house is like that on this window. Plaster walls.
7. No. 13 ^{of} **MAY 24 1977** Doc-

PROPERTY OF THE NATIONAL ARCHIVES



1. Michel Prudhomme Home
2. Opelousas, La. *St. Landry Parish*
3. Daily World Photographer **APR 5 1977**
4. July 1976
5. Kenneth Deshotel, Opelousas, La.
6. Door from back gallery (now enclosed) into room at northeast corner of house on first floor. Shows the pegging which was used in all door and window enframements.
7. No. 14 *17* **MAY 24 1977 Doc**



1. Michel Prudhomme Home
2. Opelousas, La.
3. Daily World Photographer
4. July 1976 *St. Landry Parish*
5. Kenneth Deshotel, Opelousas, La.
6. Casement window in northeast corner of house on first floor, now a bathroom. Thought to be one of original windows (except for the glass) like those which had been used across back side of first floor.
7. No. 15 *17* **MAY 24 1977** Doc-

APR 5 1977

PROPERTY OF THE NATIONAL REGISTER



1. Michel Prudhomme Home
2. Opelousas, La.
3. Daily World Photographer
4. July 1976 *St. Landry Parish*
5. Kenneth Deshotel, Opelousas, La.
6. Casement window of first floor, northeast corner room, now a bathroom.
7. No. 16 *217*

MAY 24 1977 Doc

APR 5 1977

RECORDS OF THE NATIONAL ARCHIVES



1. Michel Prudhomme Home
2. Opelousas, La.
3. Daily World Photographer
4. July 1976 *St. Landry Parish*
5. Kenneth Deshotel, Opelousas, La.
6. Original (?) mantel of upstairs center room which had been living room. This is a double fireplace and the mantel in the room behind is identical.
7. No. 17 of 17

MAY 24 1977 Doc APR 5 1977

PROPERTY OF THE NATIONAL REGISTER