

KENTUCKY HISTORIC RESOURCES INVENTORY

Site No. Fa-42

1. Historic Name(s) <u>Frederick Shryock house</u>		22. ADD/County <u>Bluegrass / Fayette</u>	
Original Owner <u>Frederick Shryock</u>		23. U.S.G.S. Quadrant (15'/75') <u>Clintonville</u> G.I.S. Mod.	
2. Present Name <u>Frederick Shryock house</u>		24. UTM Reference <u>16 733880 4215860</u>	
3. Location <u>1/2 mi W of 859, 1/4 mi S of 57, (near corners of 859)</u>		Zone Easting Northing	
4. Owner's Name <u>Charles Asbury</u>		25. Coordinate Accuracy <input type="checkbox"/>	
5. Owner's Address <u>Cleeland Road, Lexington, Ky. 40507</u>		26. Prehistoric Site Object Historic Site Structure Building <input checked="" type="checkbox"/> Other	
6. Open to Public Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	7. Visible from road Yes <input type="checkbox"/> No <input checked="" type="checkbox"/>	8. Ownership <input checked="" type="checkbox"/> Private <input type="checkbox"/> Local <input type="checkbox"/> State <input type="checkbox"/> Federal	
9. Local Contact/Organization		27. National Register District Name:	
10. Site Plan with North Arrow <u>See attached boundary form</u>		28. Significance Evaluation <input type="checkbox"/>	
11. Architect		29. Status Date	
12. Builder		National Landmark <input type="checkbox"/>	
13. Date <u>1804</u> A. <input checked="" type="checkbox"/> B. <input type="checkbox"/>		National Register <input type="checkbox"/>	
14. Style A. <u>Federal</u> <input checked="" type="checkbox"/> B. <input type="checkbox"/>		Landmark Certificate <input type="checkbox"/>	
15. Original Use <u>Residence</u> <input checked="" type="checkbox"/>		Kentucky Survey <input type="checkbox"/>	
16. Present use <u>Residence</u>		Local Landmark <input type="checkbox"/>	
17. Condition <u>fair</u> <input type="checkbox"/>		HABS/HAER <input type="checkbox"/>	
18. Description		30. Historic Theme	
<p><u>3 bay 2 story hall parlor dry stone house. Quarried stone, common masonry, boussoirs w keys, larger stones on quoined corners, water table. Mill stone set in NE end in gable with "FS, 1804" carved in</u></p> <p>(photo) (Continue on Back) (over)</p>		Primary <u>architecture</u> <input checked="" type="checkbox"/>	
		Secondary <input type="checkbox"/>	
		Other <input type="checkbox"/>	
		31. Endangered <u>by lack of repair</u> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>	
		32. Preservation Project Status <input type="checkbox"/>	
No. Stories <u>2</u> <input checked="" type="checkbox"/>		Actual Cost in \$1,000s <input type="checkbox"/>	
Single Pile <input checked="" type="checkbox"/> NA <input type="checkbox"/>		33. ATTACH PHOTO <u>in attached envelope</u>	
Double Pile <input type="checkbox"/>		Roll No. _____	
Floor Plan <u>hall-parlor</u> <input checked="" type="checkbox"/>		Picture No. _____	
Structural Fabric <u>stone</u> A. <input checked="" type="checkbox"/> B. <input type="checkbox"/>		Direction _____	
Decorative Fabric <u>boussoirs</u> A. <input checked="" type="checkbox"/> B. <input type="checkbox"/>		34. Prepared by: <u>C. M. Woolley</u>	
Roof Form <u>gable</u>		35. Organization _____	
19. History <u>House built by Frederick Shryock, brother of the builder Matthias Shryock (father of Hideron S.); family came fr Frederick Co., Maryland in 1770 S. Later owners: 1861-N. Long</u> (over)		36. Date <u>1982</u>	
20. Significance <u>Early stone house w original woodwork; typical of period; very few left in Fayette. Home of uncle of famous Ky architect, Hideron Shryock</u>		37. Revision Dates _____	
21. Source of Information <u>1977 inventory form</u>		38. Staff Review _____	

18. Cont.:

Stone; chimney interior, each gable end. Cellar entrance from NE end, no fire in cellar; attic windows flank chimneys; top plate returns on end. Pegged frames, square pills. (photo 3)

Interior has enclosed corner stair in each room, in rear corners beside fireplaces - stair has winders, no landings; no door between rooms upstairs. NE room has breakfast shelf mantel w panelled pilasters, gouged trim below frieze, panelled tablet and end blocks, gouged trim above frieze (once continuous, now spaced); press to right of mantel, door gone. SW room mantel has architrave trim & meander moldings below shelf; press to left of mantel, door gone. (photo 5)

Floor jambs panelled (2 dow. sq., 2 sq. panels), windows panelled (2 dow. sq., 1 sq. panel on jambs, 2 dow. sq. panels on heads); chair rail throughout house. (photo 6)

Sited on hillside facing slight uphill grade, above & close to branch of N. Elkhorn Creek. Spring E of house

19. Cont.:

1877-91 - W. Haley; 1904 Mrs W. Furgerson, resident.

VERBAL BOUNDARY DESCRIPTION & JUSTIFICATION

Beginning at A near the lane entrance to the yard, thence with fence around yard NW 180 ft to B, NE 155 ft to C, SE 180 ft to D at the lane, thence SW with lane 155 ft to the beginning containing only the stone house and about 2/3 acre.

SKETCH MAP OF SITE SHOWING BOUNDARIES AND KEY BUILDINGS AND FEATURES WITH NORTH ARROW.

