

Honan's Block and 112-114 Main Street  
110-114 Main Street  
Woonsocket, Rhode Island


Photographer: Lynda Reed

Date: April 1989

Negatives at: Rhode Island Historical  
Preservation Commission  
150 Benefit Street  
Providence, Rhode Island

View: Main Street elevation, view northwest.

Photo #1



18 HONAN BLOCK 73

INTERNATIONAL  
PLY-OUTLET

2 Honan's Block and 112-114 Main Street  
110-114 Main Street  
Woonsocket, Rhode Island

Photographer: Lynda Reed

Date: April 1989

Negatives at: Rhode Island Historical  
Preservation Commission  
150 Benefit Street  
Providence, Rhode Island

View: Honan's Block Main Street facade,  
view west

Photo #2





3 Honan's Block and 112-114 Main Street  
110-114 Main Street  
Woonsocket, Rhode Island

Photographer: Lynda Reed

Date: April, 1989

Negatives at: Rhode Island Historical  
Preservation Commission  
150 Benefit Street  
Providence, Rhode Island

View: South elevation detail, view north

Photo # 3



4 Homan's Block and 112-114 Main Street  
110-114 Main Street  
Woonsocket, Rhode Island

Photographer: Lynda Reed

Date: April 1989

Negatives at: Rhode Island Historical  
Preservation Commission  
150 Benefit Street  
Providence, Rhode Island

View: Cornice detail, view west.

Photo #4





5 Homan's Block 2nd 112-114 Main Street  
110-114 Main Street

Woonsocket, Rhode Island

Photographer: Lynda Reed

Date: April 1989

Negatives at: Rhode Island Historical  
Preservation Commission  
150 Benefit Street  
Providence, Rhode Island

View: Window detail, view west.

Photo # 5



6 Homan's Block and 112-114 Main Street  
110-114 Main Street  
Woonsocket, Rhode Island

Photographer: Lynda Reed

Date: April 1989

Negatives at: Rhode Island Historical  
Preservation Commission  
150 Benefit Street  
Providence, Rhode Island

View: Interior, second floor stair, view west.

Photo #6





7 Homan's Block and 112-114 Main Street  
110-114 Main Street  
Woonsocket, Rhode Island

Photographer: Lynda Reed

Date: April 1989

Negatives at: Rhode Island Historical  
Preservation Commission  
150 Benefit Street  
Providence, Rhode Island

View: Interior, second floor office, view east.

Photo # 7



8 Honan's Block and 112-114 Main Street  
110-114 Main Street  
Woonsocket, Rhode Island

Photographer: Lynda Reed

Date: April 1989

Negatives at: Rhode Island  
Rhode Island Historical  
Preservation Commission  
150 Benefit Street  
Providence, Rhode Island

View: Interior, third floor photography studio,  
view southeast.

Photo # 8