



BETHEL
Methodist
CHURCH

215

Bethel A.M.E. Church

213 W. North St

Crawfordsville

MONTGOMERY CO. IN

107 ± N

View from north to south of church's north bay, tower
on northeast corner of building, and partial view of the
parsonage east of church. Both on lot 20. [The east
end of the Northside Rec Center on Lot 19 is also
shown]

NEGS: 213 W. NORTH

Photo #1

#1A

Film 483429

May 9, 2000



Bethel A. M. E. Church

107 N

213 W. North St.

Crawfordsville MONTGOMERY CO., IN

8A

Film 983429

May 09, '00

View of church from South end of Lot 20, showing jointure of "dining room" roof to sanctuary roof on north; also kitchen addition. Also west bay of the parsonage, and closure of the upper openings of the the tower; and the east bay of the sanctuary and its adjacent west bay of the parsonage.

NEES: 213 W. NORTH

Photo #2



Bethel A. M. E. Church

107 N

213 W. North St.

Crawfordsville MONTGOMERY CO., IN

#5A

Film 983429

May 9, '00

View from north to south of north bay + porch
of parsonage and east bay of church. Partial
views of tower and north bay of church.
[The east boundary of lot is just east of the
parsonage as it goes to the south.]

PHOTO [#]3

NEGS: 213 W. NORTH.



BETHEL A.M.E. CHURCH 107 N

8A 213 W. NORTH ST., Crawfordsville MONTGOMERY CO., IN
148981

View of South end of Sanctuary - taken from middle of Sanctuary

Jy 28 '00

NEGS: 213 W. NORTH.

Photo # 4



BETHEL A. M. E. CHURCH

213 W. NORTH ST.

107 N
Crawfordsville MONTGOMERY CO. IN

A 11

Film 148981

Jy 28, '00

Close-up view of podium + furnishings in south end
of podium. View from east side of sanctuary

NEGS: 213 W. NORTH.

PHOTO # 5



BETHEL A. M. E. CHURCH

107 N

213 W. North St. Crawfordsville, MONTGOMERY CO.,
IN.

21A

Film 148981

dy 28, '00

Close-up view of northwest corner of Room 2, south of Sanctuary. Shows trap door in floor leading to cellar where fugitive slaves were hidden. [The door in the west wall is intact, but closed on outside in west bay of church.] To the right, the door opens into the southwest corner of the Sanctuary

NEG: 213 W. NORTH

PHOTO # 6



BETHEL A.M.E. CHURCH

107 N

213 W. NORTH ST. Crawfordsville, MONTGOMERY CO., IN

Window in North wall as seen from Interior

#A1


148981

Camera view from south interior of
Sanctuary

Jy 28, 2000

NEGS: 213 W. NORTH

PHOTO # 7



BANNER
CLASS

BETHEL A.M.E. CHURCH

107 N

213 W. North St. Crawfordsville, MONTGOMERY CO., IN

20A

Film 148981

Jy, 28'00

This view of the middle room, "the dining room", was taken northwest corner (trap door area) showing most of the room to the east. In the south wall is the doorway into the church's kitchen on south.

NEGS: 213 W. NORTH

PHOTO # 8