



SLAYTON MERCANTILE CO.

SLAYTON MERCANTILE CO.

GROCERIES & FURNITURE

SLAYTON MERCANTILE CO.

DRY GOODS & GIFTS

ICE  
ICE  
ICE

Slayton Mercantile

Golden Valley County

Lavina, Montana

Photographer: George Ainslie, Feb. 2000

Negative: Slayton Merc Archives

Views: East Side of Store

**SLAYTON MERCANTILE CO.**

GROCERIES & HARDWARE

**SLAYTON MERCANTILE CO.**

DRY GOODS & GIFTS

ICE  
ICE  
ICE

Slayton Mercantile

Golden Valley County

Latina, Montana

Photographer: George Ainslie, Feb. 2000

Negative: Slayton Merc Archives

View: East Side of Store

SLAYTON MERCANTILE CO.



Slayton Mercantile

Golden Valley County

Lavina, Montana

Photographer: George Ainslie, Feb. 2000

Negative: Slayton Merc Archives

View: South Side of Store



Slayton Mercantile

Golden Valley County

Lavina, Montana

Photographer: George Ainslie, Feb. 2000

Negative #: Slayton Merc Archives

View: North Side of Store





Slayton Mercantile  
Golden Valley County  
Lavina, Montana

Photographer: George Ainslie, F. Co. 2000  
Negative: Slayton Merc. Archives  
View: North Side of Store



Slayton Mercantile

Golden Valley County

Lavina, Montana

Photographer: George Ainslie, Feb 2000

Negative: Slayton Merc Archives

View: West side of store



Slayton Mercantile  
Golden Valley County  
Lavina, Montana

Photographer: George Ainslie, Feb., 2000

Negative: Slayton Merc Archives

View: Frost Killer Stove, inside main store



Slayton Mercantile

Golden Valley County

havina, Montana

Photographer: George Ainslie, Feb. 2000

Negative: Slayton Merc Archives

View: Money trolley, carried payments up to the  
office inside main store





Slayton Mercantile

Golden Valley County

Lavina, Montana

Photographer: George Ainslie, Feb. 2000

Negative: Slayton Merc Archives

View: Elevator Cage Center Rear Room of Store

A black and white photograph showing a close-up of a wooden door or panel mechanism. A metal plate is mounted on the wood, featuring a manufacturer's label. The label reads "UNION ELEVATOR & MACHINE CO. 19 CHICAGO 10". The mechanism includes various metal components such as hinges, bolts, and rods, suggesting it is part of an elevator system. The wood shows signs of wear and age.

UNION ELEVATOR  
&  
MACHINE CO.  
19 CHICAGO 10

Slayton Mercantile  
Golden Valley County  
Layna, Montana

Photographer: George Ainslie, Feb. 2000

Negative: Slayton Merc Archives

View: Detail of elevator cage showing the original  
sign on the elevator with date



Slayton Mercantile

Golden Valley County

Lavina, Montana

Photographer: George Ainslie, Feb. 2000

Negative: Slayton Merc Archives

View: up elevator shaft at the "works" of the elevator

FOIREBANKS



Slayton Mercantile  
Golden Valley County

Lavina, Montana

Photographer: George Ainslie, Feb 2000

Negative: Slayton Merc Archives

View: Fairbanks Floor Scale Rear Room of Store





Slayton Mercantile  
Golden Valley County  
Lavina, Montana

Photographer: George Ainslie, Feb, 2000

Negative: Slayton Merc Archives

Closeup view of elevator works



Slayton Mercantile  
Golden Valley County  
Lavina, Montana

Photographer: George Ainslie, Feb 2000

Negative: Slayton Merc Archives

View: Tin ceiling in the main store room



Slayton Mercantile  
Golden Valley County  
Lavina, Montana

Photographer: George Ainslie, Feb. 2000

Negative: Slayton Merc Archives

View: West rear door from inside the rear room  
of store



PU

ARE YOU A FARMER  
EMIGRANT OR  
WORK  
AN AGRICULTURIST

PLEASE CALL OR COME  
TO  
THE MONTANA MUSEUM  
FARMWORKS  
315 3RD AVENUE  
BILLINGS MONTANA  
400-215-1000  
EXAMPLES OF

EDUCATION  
TRAINING  
DIRECT OR INDIRECT  
IMMUNIZATIONS  
PAP SMears  
DENTAL  
SUBSTANCE ABUSE  
VIBRIOSIS SCIENTISTS  
WILLIAMS CHILDREN'S  
WELLS  
CONSTITUTIONAL  
NUTRITION  
WELLNESS SERVICES  
MUNICIPALITY  
SMALL HEAT TREATING

Slayton Mercantile  
Golden Valley County  
Lavina, Montana

Photographer: George Ainslie, Feb. 2000  
Negative: Slayton Merc Archives

View: Original Front Doors in the Store with Brass  
Thumb Latch