

Photographer - Duane Garrett NOV 7 1977 1977 Idaho State Historical Society

0. W. Smith building, view from the northeast (#16)

Site survey collection.



Photographer - Duane Garrett 1977 Idaho State Historical Society

Falk Warehouse (22), Carson & Lusk Warehouse (21), Idaho Candy (20), and Idaho Milling and Elevator (19) from the northwest.



- South Eighth Street Historic District Boise, Idaho
- Photographer Duane Garrett 1977 Idaho Historical Society
- View of the Antom Gøreczky block (#8, and #9) from the northwest.
- Site survey.





Photographer - Duane Garrett 1977 Idaho State Historical Society

View of the Fritchman Warehouse (#6) and Davis Warehouse (#5) from the southwest.



Photographer - Duane Garrett 1977 Idaho State Historical Society

View of the Fritchman building (3) and Boise Ice and Produce (4) from the southwest.



Photographer - Duane Garrett 1977 Idaho State Historical Society

The Mutual Creamery viewed from the northeast, (1).



Photographer - Don Hibbard 1977 Idaho State Historical Society

View from the north looking at west side of 8th Street.





Photographer - Duane Garrett 1977 Idaho State Historical Society

View of the Boise Junk House (17) from the southeast in background left Northrup King (2), right 0. W. Smith building (16). PHOTO

NOV 7 1977

7 01 8