



AZTEC RUINS NM VISITOR CENTER

AZTEC RUINS NM, SAN JUAN CO., NM

PHOTOGRAPHER: J. CAYWOOD (HRA) 9/17/95

VIEW TO: NORTH SOUTH ELEVATION OF 1958
MUSEUM ADDITION

LOCATION OF NEGATIVE: NPS, DENVER, CO.

photo 2



AZTEC RUINS NM VISITOR CENTER

AZTEC RUINS NM, SAN JUAN CO., NM

PHOTOGRAPHER: J. CLYWOOD (HRA) 9/17/1995

VIEW TO: NW, South Entrance.

LOCATION OF NEGATIVE: NPS, DENVER, CO.

Photo 1



AZTEC RUINS VISITOR CENTER

AZTEC RUINS NM, SAN JUAN CO., NM

PHOTOGRAPHER: J CAYWOOD (HRA) 9/17/1995

VIEW TO: NORTH; south elevation of restroom
additions (1958 and 1988)

LOCATION OF NEGATIVE: NPS, DENVER, CO

photo 3



AZTEC RUINS NM VISITOR CENTER

AZTEC RUINS NM, SAN JUAN CO., NM

PHOTOGRAPHER: J. CAYWOOD (HRA) 9/17/1995

VIEW TO: EAST, SOUTH ELEVATION PORCH

LOCATION OF NEGATIVE: NPS, DENVER, CO

photo 4



AZTEC RUINS NM VISITOR CENTER

AZTEC RUINS NM, SAN JUAN CO., NM

PHOTOGRAPHER: J. CAYWOOD (HRA) 9/17/1995

VIEW TO: (WNW); EAST ELEVATION of 1958
museum addition

LOCATION OF NEGATIVES: NPS, DENVER, CO

photos



AZTEC RUINS NM VISITOR CENTER

AZTEC RUINS NM, SAN JUAN CO., NM

PHOTOGRAPHER: J. CAYWOOD (HRA) 9/17/1995

VIEW TO: SW - REAR (NORTH) ELEVATION PORCH

LOCATION OF NEGATIVES: NPS, DENVER, CO

photo 6



AZTEC RUINS NM VISITOR CENTER

AZTEC RUINS, NM, SAN JUAN CO., NM

PHOTOGRAPHER: J. CAYWOOD (HRA) 9/17/1995

VIEW TO: SW - NORTH ELEVATION OF LIBRARY &
CURATIONAL STORAGE ADDITIONS

LOCATION OF NEGATIVES: NPS, DENVER, CO

photo 7



AZTEC RUINS NM VISITOR CENTER

AZTEC RUINS NM, SAN JUAN CO., NM

PHOTOGRAPHER: J. CAYWOOD (HRA) 9/17/1995

VIEW TO: EAST - STAIRWELL TO BASEMENT ON
NORTH ELEVATION

LOCATION OF NEGATIVES: NPS, DENVER, CO

photos



CHILDREN
Earn a badge
Ask ranger how

Donations will help
preserve and interpret
Aztec Ruins National Monument

Wheelchair Available

No Smoking Please

Informational brochures and pamphlets displayed on a rack.

AZTEC RUINS NM VISITOR CENTER

AZTEC RUINS NM, SAN JUAN CO., NM

PHOTOGRAPHER: J. CAYWOOD (HRA) 9/17/1995

VIEW TO: NW- INTERIOR OF LOBBY
INFORMATION COUNTER

LOCATION OF NEGATIVES: NPS, DENVER, CO

photo 9



AZTEC RUINS NM VISITOR CENTER

AZTEC RUINS NM, SAN JUAN CO., NM

PHOTOGRAPHER: J. CAYWOOD (HRA) 9/17/1995

VIEW TO: NE - INTERIOR OF ³_R LOBBY/VIDEO ROOM

LOCATION OF NEGATIVES: NPS, DENVER, CO

photo 10

EXCAVATION

THE EXCAVATION OF THE TOMB OF THE VIRGIN MARY



THE EXCAVATION OF THE TOMB OF THE VIRGIN MARY

THE EXCAVATION OF THE TOMB OF THE VIRGIN MARY



MUSEUM OF
UNCLAN
RELIGION

MUSEUM OF
UNCLAN
RELIGION

MUSEUM OF
UNCLAN
RELIGION



MUSEUM OF
UNCLAN
RELIGION

MUSEUM OF
UNCLAN
RELIGION

MUSEUM OF
UNCLAN
RELIGION

AZTEC RUINS NM VISITOR CENTER

AZTEC RUINS NM, SAN JUAN CO., NM

PHOTOGRAPHER: J. CAYWOOD (HRA) 9/17/1995

VIEW TO: NORTH - INTERIOR OF EXHIBIT ROOM
MUSEUM CONSTRUCTED IN 1958

LOCATION OF NEGATIVES: NPS, DENVER, CO

photo 11



AZTEC RUINS NM VISITOR CENTER

AZTEC RUINS NM, SAN JUAN CO., NM

PHOTOGRAPHER: J. CAYWOOD (HRA) 9/17/1995

VIEW TO: NE - INTERIOR OF LIBRARY / WORK ROOM

LOCATION OF NEGATIVES: NPS, DENVER, CO

photo 12



AZTEC RUINS NM VISITOR CENTER

AZTEC RUINS NM, SAN JUAN CO., NM

PHOTOGRAPHER: J. CAYWOOD (HRA) 9/17/1995

VIEW TO: SW - INTERIOR OF WOMEN'S RESTROOM

LOCATION OF NEGATIVES: NPS, DENVER, CO

photo 13



CAUTION

23

AZTEC RUINS NM VISITOR CENTER

AZTEC RUINS NM, SAN JUAN CO., NM

PHOTOGRAPHER: J. CAYWOOD (HRA) 9/17/1995

VIEW TO: WEST - INTERIOR OF CISTERN

LOCATION OF NEGATIVE: NPS, DENVER, CO

photo 14



AZTEC RUINS NM PARKING LOT AND
PERIMETER WALL

AZTEC RUINS NM, SAN JUAN CO., NM

PHOTOGRAPHER: J. CAYWOOD (HRA) 9/17/1995

VIEW TO: NE

LOCATION OF NEGATIVES: NPS, DENVER, CO

PHOTO 15



AZTEC RUINS NM, Rear Landscaped area

AZTEC RUINS NM, SAN JUAN CO., NM

Photographer: J. Caywood, 9/17/1995

View to: SSW

Location of negatives: NPS, Denver CO
photo 16



AZTEC RUINS NM - REAR LANDSCAPING

AZTEC RUINS NM, SAN JUAN CO., NM

photographer: J. Caywood 9/17/1995

View to: West

Location of negative: NPS Denver, CO
photo 17