



ALEXANDER AND JAMES LINN HOMESTEAD 1 of 16
Mine Brook Road, Far Hills Borough
Somerset County, N.J.

Photographer: Ursula C. Brecknell
(has negatives) January 1985
looking easterly



ALEXANDER AND JAMES LINN HOMESTEAD #1A. 16
Mine Brook Road, Far Hills Borough
Somerset County, N.J.

Photographer: Ursula C. Brecknell (has
negatives) January 1985

looking northwesterly



ALEXANDER AND JAMES LINN HOMESTEAD
Mine Brook Road, Far Hills Borough
Somerset County, N.J.

2 of 16

Photographer: Ursula C. Brecknell
January 1985 (has negatives)

looking south, slightly eastward



ALEXANDER AND JAMES LINN HOMESTEAD
Mine Brook Road, Far Hills Borough
Somerset County, N.J.

#2A 11

Photographer: Ursula C. Brecknell (has
negatives) January 1985

looking north to barn



ALEXANDER AND JAMES LINN HOMESTEAD 3 of 16
Mine Brook Road, Far Hills Borough
Somerset County, N.J.

Photographer: Ursula C. Brecknell (has
negatives) January 1985

looking southwesterly



ALEXANDER AND JAMES LINN HOMESTEAD
Far Hills, Somerset Co., N.J.

Photographer: Arthur Brecknell
Summer 1985

negative in photographer's possession

Joined barns, with view of house
facing south

Photograph # 3A

Photography
by
Arthur W. Brecknell



ALEXANDER AND JAMES LINN HOMESTEAD 4 of 16
Mine Brook Road, Far Hills Borough
Somerset County, N.J.

Photographer: Ursula C. Brecknell (has
negatives) January 1985

looking easterly



ALEXANDER AND JAMES LINN FARMSTEAD
Far Hills, Somerset Co., N.J.

Photographer: Arthur Brecknell
Summer 1985

negative in photographer's possession

View of main barn facing east-north

Photograph #4A

Photography
by
Arthur W. Brecknell



ALEXANDER AND JAMES LINN HOMESTEAD
Mine Brook Road, Far Hills Borough
Somerset County, N.J.

5 of 16

Photographer: Ursula C. Brecknell (has
negatives) January 1985

wing facade, looking east, slighty south



ALEXANDER AND JAMES LINN HOMESTEAD
Far Hills, Somerset Co, N.J.

Photographer: Arthur Brecknell
Summer 1985

negative in photographer's possession
Barn: ^{Bay to east of} center bay, facing north

Photograph #5A

Photography
by
Arthur W. Brecknell



ALEXANDER AND JAMES LINN HOMESTEAD 6 of 16
Mine Brook Road, Far Hills Borough
Somerset County, N.J.

Photographer: Ursula C. Brecknell (has
negatives) January 1985

door in storage cupboard under chimney arch



ALEXANDER AND JAMES LINN HOMESTEAD
Mine Brook Road, Far Hills Borough
Somerset County, N.J.

#6A

Photographer: Ursula C. Brecknell (has
negatives) January 1985

chicken coop, looking southeasterly



ALEXANDER AND JAMES LINN HOMESTEAD
Far Hills, Somerset Co., N.J.

Photographer: Arthur Brecknell
Summer-1985

negative in photographer's possession

Shooting south from north front room,
across center hall to fireplace in south
front room. Old transom; paneled door

Photograph 7 of 16.

Photography
by
Arthur W. Brecknell



ALEXANDER AND JAMES LINN HOMESTEAD
Far Hills, Somerset Co., N.J.

Photographer: Arthur Brecknell
Summer 1985

Main room in wing, showing fireplace and
garret stair door against north wall.
Dividing wall for rear room recently re-
moved; ceiling removed.

Photograph 8 of 16
negative in photographer's possession

Photography
by
Arthur W. Brecknell



ALEXANDER AND JAMES LINN HOMESTEAD 9 of 16
Mine Brook Road, Far Hills Borough
Somerset County, N.J.

Photographer: Ursula C. Brecknell (has
negatives) January 1985

exposed first storey wall, rear exterior
(framed, under glass)



ALEXANDER AND JAMES LINN HOMESTEAD
Far Hills, Somerset Co., N.J.

Photographer: Arthur Brecknell
Summer 1985

negative in photographer's possession

UDownstairs center hall, shooting to rear
(east), showing niche created for stair
flight and new rear room

Photographer 10 of 16

Photography
By
Arthur W. Brecknell



ALEXANDER AND JAMES LINN HOMESTEAD
Far Hills, Somerset Co., N.J.

Photographer: Arthur Brecknell
Summer 1985

Negatives in photographer's possession

Upstairs hall, looking west, showing stair
well, attic balustrade and Greek-style
doors.

Photograph 11 of 16

Photography
By
Arthur W. Brecknell



ALEXANDER AND JAMES LINN HOMESTEAD
Far Hills, Somerset Co., N.J.

Photographer: Arthur Brecknell
Summer 1985

negative in photographer's possession

front room north division of cellar, showing paired support system for center hall above. Cinderblock wall recent replacement for wall of daub and lath. Doorway at right to south cellar. Photograph 12 of 16

Photography
by
Arthur W. Brecknell



ALEXANDER AND JAMES LYNN HOMESTEAD
Far Hills, Somerset Co., N.J.

Photographer: Arthur Brecknell
Summer 1985

negative in photographer's possession

Cellar dividing wall, showing old sill and
raised floor level beyond (shooting north)

Photograph 13 of 16

Photography

By

Arthur W. Brecknell



ALEXANDER AND JAMES LINN HOMESTEAD
Far Hills, Somerset Co., N.J.

Photographer: Arthur Brecknell
Summer 1985

negatives in photographer's possession

Lintel log and boarded pier of deep cooking fireplace (one of two) in cellar in south room (shooting south wall)

Photographs 14 of 16

Photography
by
Arthur W. Brecknell



ALEXANDER AND JAMES LINN HOMESTEAD
Mine Brook Road, Far Hills Borough
Somerset County, N.J.

15 of 16.

Photographer: Ursula C. Brecknell (has
negatives) January 1985

wall of plastered daub, filling chimney
arch in rear east room



ALEXANDER AND JAMES LINN HOMESTEAD
Far Hills, Somerset Co., N.J.

Photographer: Arthur Brecknell
Summer 1985

negative in photographer's possession

Lefted bents, for the roof of house
facing south

Photograph 16 of 16

Photography
by
Arthur W. Brecknell