

Zula Linklater House
Hillsboro, Oregon
Photographer Unknown
1923

Neg. Location: Partin & Hill Architects
Hillsboro, ^{209 NE Lincoln,} OR 97123

Front facade, oriented to the west
Photo No. 1




Zula Linklater House Neighborhood
Hillsboro, Oregon

Photographer: Carey Vanderzandt.
1983

Negative Location: Partin & Hill Archit.
Hillsboro, Oregon ^{209 NE Lincoln} 97123

Mission style Masonic Lodge (rt),
Carnegie Library (left) along Second
Avenue

Photo No. 2



Zula Linklater House

Hillsboro, Oregon

Photographer: Carey Vanderzandt

October 1983

Neg. Location: Partin & Hill Architects
Hillsboro, Oregon ^{205 NE LINCOLN} 97123

Zula Linklater House, front facade along
Second Avenue, western orientation

Photo No. 3



Zula Linklater House

Hillsboro, Oregon

Photographer: Carey Vanderzandt

October 1983

Neg. Location: Partin & Hill Architects
Hillsboro, Oregon ^{209 NE Lincoln} 97123

Zula Linklater House, south elevation.

Photo No. 4



Zula Linklater House

Hillsboro, Oregon

Photographer: Carey Vanderzandt

October 1983

Neg. Location: Partin & Hill Architects
Hillsboro, ^{209 NE LINCOLN} OR 97123

Rear elevation (east)

Photo No. 5



Zula Linklater House

Hillsboro, Oregon

Photographer: Carey Vanderzandt

October 1983

Neg. Location: Partin & Hill Architects
Hillsboro, ^{209 NE LINCOLN} OR 97123

South and east elevations. Carnegie
Library in foreground

Photo No. 6



Zula Linklater House

Hillsboro, Oregon

Photographer: Carey Vanderzandt

October 1983

Neg. Location: Partin & Hill Architects
Hillsboro, ^{209 NE LINCOLN} OR 97123

Rear elevation (east) and northern elevation
to right.

Photo No. 7



Zula Linklater House

Hillsboro, Oregon

Photographer: Carey Vanderzandt

October 1983

Neg. Location: Partin & Hill Architects
Hillsboro, ^{209 NE LINCOLN} OR 97213

View from living room looking into
central hallway and dining room.

Photo No. 8



Zula Linklater House

Hillsboro, Oregon

Photographer: Carey Vanderzandt

October 1983

Neg. Location: Partin & Hill Architects
Hillsboro, Oregon ^{209 NE LINCOLN} 97123

Interior, second story central hallway
looking west into sewing room.

Photo No. 9