United States Department of the Interior National Park Service

National Register of Historic Places Inventory—Nomination Form

For NPS use only received JAN 3 0 1984 date entered

See instructions in *How to Complete National Register Forms*Type all entries—complete applicable sections

Type an entire	23 Complete applicable	300110113			
1. Nan	ne				
historic Ban	k of Jersey				
and or common	n Same				
2. Loc	ation				
street & numbe	er Main St reet				N/A not for publication
city, town J	ersey	N/A	vicinity of		
state Georg	ia co	ode 013	county	Walton	code 297
3. Clas	ssification				
Category district _X building(s) structure site object	Ownership public private both Public Acquisition N/A in process being considered	wo Access _X_ yes	occupied rk in progress	Present Use agriculture commercial educational entertainment government industrial military	museum park private residence religious scientific transportation X other: Dentist's
4. Owi	ner of Prope	ertv			Office
name Will	iam C. McGarity, M	.D.			
street & number	r 934 Artwood Roa	d, N.E.			
city, town At	lanta	N/A	vicinity of	sta	te Georgia 30307
<u>5. Loc</u>	ation of Leg	gal De	scripti	on	
courthouse, reg	jistry of deeds, etc. Supe	erior			
street & number	r Walton County Co	urthouse			
		ar choase			- Coordia
city, town Mon		in Ev	ictina	Star	te Georgia
	resentation		isting	Surveys	
Histori title Walton	c Structures Field County	Survey:	has this pro	pperty been determined	l eligible? yes _X_ no
date 1977				federal X	state county local
depository for s	survey records Histori	c Preserva	ition Secti	on, Georgia Dept.	of Natural Resources
city, town At	lanta			stat	te Georgia

7. Description

Condition excellent	deteriorated	Check one unaltered	Check one _X original s	iite
X good fair	ruins unexposed	_X_ altered	moved	date

Describe the present and original (if known) physical appearance

The Bank of Jersey is a small one-story late-Victorian-style commercial building dating from 1904. The building is built of load-bearing brick, laid in running bond. The major exterior features are the door and a large twelve-over-twelve window on the front facade, both with stone lintels, and a similar window on each side, close to the east front. All three windows retain their original metal grilles. Pilaster-like corner brickwork, a corbeled cornice and a parapet roof with a corbeled cap that steps down toward the rear complete the detailing. The interior, originally one room divided by a teller's cage (removed in the 1930s), was remodeled for a dentist's office in 1981; the original tongue-and-groove ceiling remains, but the wood floor has been replaced and brick walls have been covered. The shutters and door hood were added to the exterior in 1981. The Bank is located on a corner lot at the center of the tiny hamlet of Jersey. A historic general store is located across an unpaved road to the building's south and a historic residence is located across the main paved road to the east. The setting is rural with open fields to the north and west.

Photographs

The Historic Preservation Section has determined that the photographs taken in August, 1982, still accurately represent the character and appearance of the property. No major changes have been made to the building since then.

8. Significance

1500–1599 1600–1699 1700–1799 1800–1899	J,	community planning landscape architecture reconservation law some economics literature some education military some engineering music holds are exploration/settlement philosophy the industry politics/government tr	cience culpture ocial/ umanitarian
Specific dates	1904	Builder/Architect Unknown	

Statement of Significance (in one paragraph)


The Bank of Jersey is significant in terms of architecture as an example of a turn-of-the-century, late-Victorian-style, rural commercial structure in Walton County and in terms of commerce as the home of Jersey's only historic bank. These areas of significance support property eligibility under National Register criteria A and C.

The Bank of Jersey illustrates a style, building materials and construction techniques typical for such a commercial building in a tiny rural community. It appears modest when compared with bank buildings constructed at the same time in larger communities, but it is entirely consistent with other rural commercial structures. Its brick construction and exterior brick detailing, including the corbeling and pilaster-like corners, identify it as an important structure in a small rural community dominated by wood-frame buildings. The bank building is a landmark in Jersey, one of two historic commercial buildings left from a handful which used to mark the center of this tiny hamlet. Jersey was an agricultural supply community that had developed well before the Civil War. In the 1880s it applied for and received its first post office, and in 1905 it was incorporated, the city limits extending one-half mile in all directions from a point in the center of the road in front of the Bank of Jersey.

In terms of commerce, the building is significant as the home of Jersey's only bank and one of its most important commercial establishments which operated from 1904 to 1931. The bank served the local farmers and planters at a time before automobiles made the larger neighboring communities more accessible. It was organized by Josiah Blasingame, Sr., a locally prominent landholder and businessman who served as Jersey's first postmaster and later its first mayor. It is relatively unusual in Georgia for such a small community as Jersey to have its own local bank. The bank failed in 1931, during the Depression, and the building was used for storage until 1981.

9.	Ma	jor Bib	liogra	phica	I Ref	erer	1ces	5			
	1982. Sams, <i>A</i>	ty, Willian On file Anita B. <u>V</u> General Cha	at State l layfarers	Historic l <u>in Walton</u>	Preserva : <u>A</u> <u>Hi</u>	ation 0: story o	ffice, <u>Walt</u>	Atlan <u>on Cou</u>	ta, Geo nty, <u>G</u> e	orgia.	
10	. G	eograp	hical	Data					·		
Quad	-	minated prope ame <u>Jersey</u> es	-					Quadra	angle sca	ale <u>1:24,</u>	000
Zor C E G		4 ₁ 0 5 ₁ 4 ₁ 0 sting	3 7 3 4 Northing			Zone D H	Eastin	g	Nort	thing	
(The nor consist	dary description and the attention to th	pperty, ou acreage pr scription	tlined wi esently a of the pr	ssociatoperty.	ed with	the b	uildin	g and o	losed su coincide	rvey map, s with the
state	N/A			code	count		-			code	
state				code	count	·V				code	
	ization	arolyn Brod Historic D Georgia D e r 270 Wasi	Preservati ept. of Na	on Section tural Res	n ources	d		(101	20 , 19		
city or	r town	Atlanta				s	tate ^G	eorgia	30334		
		ate Hi				tion	Offi	cer	Cer	tifica	tion
The ev	valuated	significance o	f this propert		state is:						
665), I accore	hereby i	ated State Hist nominate this he criteria and Preservation (property for i procedures s	nclusion in the	ne Nationa ne Nationa	l Register Il Park Se	and cer	tify that			
		Historic P			Keth A.	Lyon	A3	date	دا،	5/84	
		certify that the	Buhi	included in ti	he Nationa	I Register		date	3/	7/84	
	test:		g.:					date	, 1		
		gistration									

GPO 894-785



MONROE -JERSEY RD

BANK OF JERSEY Jersey, Walton County, Georgia

PROPERTY SKETCH MAP

Source: Surveyor's Map

Scale: 1": 30'
Date: 1981
North:

Property Boundary: