


AUDITORS BUILDING COMPLEX (Annex # 3)

--Washington, D.C.

--Stuart Mac Donald, photographer --June 18, 1973

--Negative at GSA, Washington, D.C.
--North and west elevations (from NW corner)



APR 2

3:4

AUDITORS BUILDING COMPLEX (Annex # 3)

--Washington, D.C.

--Stuart Mac Donald, photographer

--June 18, 1973

-- Negative at GSA, Washington, D.C.

--North elevation



AUDITORS BUILDING COMPLEX (Annex # 3)

--Washington, D.C.

-- Stuart Mac Donald, photographer 3419

--June 18, 1973

-- Negative at GSA, Washington, D.C.

--West elevation



4:4 APR 27 1978

AUDITORS BUILDING COMPLEX (Annex # 3)

--Washington, D.C. --Stuart Mac Donald, photographer 4919 --June 18, 1973

--Negative at GSA, Washington, D.C. --East elevation from southeast corner



-- AUDITORS BUILDING COMPLEX (Annex # I)

--Washington, D.C.

-- Stuart Mac Donald, photographer 5419

-- June 18, 1973

--Negative at GSA, Washington, D.C. --West elevation (close-up)



Auditors Building Complex (Annex # I) -- Washington, D.C.

--Stuart Mac Donald, photographer 6919

--June I8, I973
--Negative at GSA, Washington, D.C.

--Negative at GSA, Washington, D,C. --South and west elevations from SW corner




-- AUDITORS BUILDING COMPLEX (Annex # I)

--Washington, D.C.

--Washington, D.C. --Stuart Mac Donald, photographer 7,19

--Negative at GSA, Washington, D.C. --South elevation from SW corner



AUDITORS BUILDING COMPLEX (Annex # I)

-- Washington, D.C.

-- Stuart Mac Donald, photographer -- June 18, 1973

-- Negative at GSA, Washington, D.C. --Northwest corner



APR 27 1978

5:5

--AUDITORS BUILDI NG COMPLEX (Annex # 2)
--Washington, D.C.

--Stuart Mac Donald, photographer 9,17

--June 18, 1973

--Negative at GSA, Washington, D.C. --North elevation, (eastern end)



APR 27 1978

3:5 -- AUDITORS BUILDING COMPLEX (Annex # 2) --Washington, D.C. -- Stuart Mac Donald, photographer 10 419

--June 18, 1973

--Negative at GSA, Washington, D.C. --South facade from southeast corner



APR 27 1978 1:5

-- AUDITORS BUILDING COMPLEX (Annex # I)

--Washington, D.C.

--Stuart Mac Donald, photographer 11419

--Negative at GSA, Washington, D.C.

98-074-11



APR 27 1978

- --AUDITORS BUILDING COMPLEX (Annex # 2)
- --Washington, D.C.
- -- Stuart Mac Donald, photographer 12 919
- --June 18, 1973
- -- Negative at GSA, Washington, D.C.
- -- East elevation



--AUDITORS BUILDING COMPLEX (Annex # 2)

-- Washington, D.C.

-- Stuart Mac Donald, photographer 13 4 19

-- June 18, 1973

-- Negative at GSA, Washington, D.C.

-- South and West elevation from SW corner



--AUDITORS BUILDING COMPLEX (Annex # 2)

--Washington, D.C.
--Stuart Mac Donald, photographer 14 919
--June 18, 1973

--Negative at GSA, Washington, D.C. --East elevation (close-up)



- -- Auditors Building Complex (Main Building)
- --Washington, D.C.
- --Stuart Mac Donald, photographer 15 9 19
- --June 18, 1973
- -- Negative at GSA, Washington, D.C.
- -- East elevation from NE corner



- -- Auditors BuildingComplex (Main Building)
- -- Washington, D.C.
- --Stuart Mac Donald, photographer 16 9/9
- --June 18, 1973
- -- Negative at GSA, Washington, D.C.
- --Northeast pavilion and tower (NE corner)



- -- Auditors Complex (Main Building)
- -- Washington, D.C.
- --Stuart Mac Donald, photographer 17 a 19
- --June18, 1973
- -- Negative at GSA, Washington, D.C.
- -- North elevation from northwest



--Auditors Building Complex (Main Building)

--Washington, D.C.

--Stuart Mac Donald, photographer 18 9 19

--June 18, 1973

-- Negative at GSA, Washington, D.C.

-- East and north elevations (from NE corner)



- -- Auditors Building Complex (Main Building)
- -- Washington, D.C.
- --Stuart Mac Donald, photographer /9 4/9
- -- Negative at GSA, Washington, D.C.
- --Southeast corner