

U-1105

St. Mary's, MD

Drawing source: Unknown date: late WWII
(ca. 1944-45)

Cited in report by Pokusha & Shonette 1994.

Standard Type VII-C German submarine.



U-1105

St. Mary's Co., MD

Photographer: unknown Date: June 3, 1944

Original located at Naval Historical Center, Wash. DC.

Commissioning of U-1105.



U-1105

St Mary's Co, MD


5404

Photographer: Unknown date: Sept 19, 1949
Original located at Naval Historical Center
Wash. D.C.

Top - U-1105 prepared for test

Middle - actual detonation 12:30pm

Bottom - U-1105 sinking



U-1105

St. Mary's Co, MD

Photographer: Unknown date Sept. 19, 1949
Original located at Naval Historical Center, Wash.-D.C.

Suspending bomb below hull of U-1105.

Looking from bow toward stern.

Range pole (striped) is part of bomb
test.

EX-102 NN 9 7178




U-1105

St. Mary's Co, MD

Photographer: Unknown date: May 10, 1945

Original located at Naval Historical Center
Wash DC.

Surrender of U-1105



U-1105

St. Mary's Co, MO

Photographer: Unknown date: 1945

Original located at Naval Historical Center,
Wash. DC

U-1105 off Coast of Ireland.




U-1105

St. Mary's Co, MD

Photographer: Unknown date; Spring, 1945

Original located at Naval ~~Historical~~ Historical Center,
Wash. DC.

Crew of U-1105




U-1105

St. Mary's Co, MD

Drawing: James Christley date: 1991
Original in Christley's possession (CT)
Photo of sketch: Susan Langley

U-1105 Embedded in bottom of
Potomac River - bow is downstream.



U-1105


St. Mary's Co, MD

Drawing: Michael Pokuski date: 1993

Original in possession of Pokuski

Photograph: Susan Langley

Housing in conning tower for radar
unit (Hohentweil - U FuMO 61)



U-1105

St. Mary's Co, MD

Photographer: Michael Potuski; Oct 9/93

Originals at Maryland Historical Trust.

Top - splash guard on conning tower

Bottom - radar housing



U-1105

St. Mary's Co, MD

photographer: Michael Poluski Oct 9/93

Original at MD Historical Trust.

Sky periscope - marine growth wiped
off to check condition of metal,
note - prism intact in top.




U-1105

St. Mary's Co, MD

Photographer: Michael Pohuski Oct 9/93
Original at MD Historical Trust

wooden declivity in situ



U-1105

St. Mary's Co, MD

Photographer: Michael Pankuski Oct 9/93
Original at MD Historical Trust

Ammunition canister in deck of
conning tower.