



Name: THE BANK HOUSE Kent County

Location: 119 North Walnut St., Milford, Delaware

Photographer: Jean Athan

Date: 10-77

Location of Negative: Division of Historical & Cultural
Affairs, OAHP, Hall of Records, Dover, De.

Description:

View of the facade which faces west.

Photograph Number:

K-167

(1)

814

NOV 18 1977

JUL 31 1978



Name: THE BANK HOUSE KENT County

Location: 119 N. Walnut St., Milford, De.

Photographer: Jean Athan

Date: 10-77

Location of Negative: Division of Historical & Cultural
Affairs, OAHP, Hall of Records, Dover, De.

Description:

View of the front entrance portico.

Photograph Number:

NOV 18 1977

K-167 (2) 814 JUL 31 1978



Name: BANK HOUSE

Kent Co.

Location: 119 N. Walnut St., Milford, DE

Photographer: Jean Athan

Date: 10/77

Location of Negative: DHCA; B/A&HP; Hall of Records,
Dover, DE

Description: View of the rear elevation.

Photograph Number:

K-167 (#3) 8¹⁴

NOV 18 1977

JUL 31 1978



Name: BANK HOUSE Kent County

Location: 119 N. Walnut Street, Milford, DE

Photographer: Jean Athan

Date: 10/77

Location of Negative: DHCA; B/A&HP; Hall of Records,
Dover, DE

Description: View of the facade and northern elevation.

Photograph Number: K-167 (#4) ¹⁴ NOV 18 1977

JUL 31 1978



Name: BANK HOUSE KENT CO.

Location: 119 N. Walnut Street, Milford, DE

Photographer: Jean Athan

Date: 10/77

Location of Negative: DHCA; B/A&HP; Hall of Records,
Dover, DE

Description:
View of marble-front fireplace in
drawing room.

Photograph Number: K-167 (#5) 14

JUL 31 1978

NOV 18 1977



Name: BANK HOUSE Kent County

Location: 119 N. Walnut Street, Milford, DE

Photographer: Jean Athan

Date: 10/77

Location of Negative: DHCA; B/A&HP; Hall of Records,
Dover, DE

Description:

Detail of gesso work on the ceiling
of the drawing room.

Photograph Number: K-167 (#6) 814

JUL 31 1978

NOV 18 1977



JUL 31 1978

Name: BANK HOUSE

KENT County

Location: 119 N. Walnut Street, Milford, DE

Photographer: Jean Athan

Date: 10/77

Location of Negative: DHCA; B/A&HP; Hall of Records, Dover.

Description: View of interior door in the drawing room.

Photograph Number: K-167 (#7) 214 NOV 18 1977



Name: BANK HOUSE

KENT COUNTY

Location: 119 N. Walnut Street, Milford, DE

Photographer: Jean Athan

JUL 31 1978

Date: 10/77

Location of Negative: DHCA; B/A&HP; Hall of Records, Dover.

Description: View of first-floor center hallway.

Photograph Number: K-167 (#8) g 14

NOV 18 1977



Name: BANK HOUSE Kent County

Location: 119 N. Walnut Street, Milford, DE

Photographer: Jean Athan

Date: 10/77

Location of Negative: DHCA; B/A&HP; Hall of Records, Dover.

Description: View of door leading to the drawing room.

Photograph Number: K-167 (#9) 2/4 NOV 18 1977

JUL 31 1978



Name: BANK HOUSE

Kent County

Location: 119 N. Walnut Street, Milford, DE

Photographer: Jean Athan

Date: 10/77

Location of Negative: DHCA; B/A&HP; Hall of Records,
Dover, DE.

Description:




JUL 31 1978

Detail of interior shutters in the first-floor
sitting room.

Photograph Number:

K-167 (#10) 814

NOV 18 1977



Name: BANK HOUSE

Kent County

Location: 119 N. Walnut Street, Milford, DE

Photographer: Jean Athan

Date: 10/77

Location of Negative: DHCA; B/A&HP; Hall of Records,
Dover, DE

JUL 31 1978

Description:

View of kitchen fireplace and wall cupboard.

Photograph Number: K-167 (#11) 9/14

NOV 18 1977



Name: BANK HOUSE

Kent, County

Location: 119 N. Walnut Street, Milford, DE

Photographer: Jean Athan

Date: 10/77

Location of Negative: DHCA; B/A&HP; Hall of Records, Dover.

Description: View of dining room fireplace.

JUL 31 1978

Photograph Number: K-167 (#12) 914

NOV 18 1977



Name: BANK HOUSE

Kent County

Location: 119 N. Walnut Street, Milford, DE

Photographer: Jean Athan JUL 31 1978

Date: 10/77

Location of Negative: DHCA; B/A&HP; Hall of Records, Dover.

Description: View of window (in first-floor sitting room)
embrasured with heavily moulded architrave.

Photograph Number: K-167 (#13)

^{8/14}
NOV 18 1977



Name: BANK HOUSE

Kent County

Location: 119 N. Walnut Street, Milford, DE

Photographer: Jean Athan

Date: 10/77

Location of Negative: DHCA; B/A&HP; Hall of Records, Dover.

Description: View of second-floor fireplace.

Photograph Number: K-167 (#14) 914

JUL 31 1978

NOV 18 1977