



83-A-4

Jericho Center Historic District

Jericho, Vermont

Credit: Nancy E. Boone

Date: January 1983

Negative filed at Vermont Division for
Historic Preservation

Description: View Northeast including the
northeast side of the Village Green, (L-R)

Building #'s 21,22,23,24A,24,25

Photo: #1



Jericho Center Historic District

Jericho, Vermont

Credit: Adele Cramer

Date: March 1977

Negative filed at Vermont Division for
Historic Preservation

Description: View north including the west
side of the Village Green and Buildings #4,5,
7,8,20, & 21

Photo: #2

Streetscape 2



Jericho Center Historic District

Jericho, Vermont

Credit: Gina Campoli

Date: August 1982

Negative filed at Vermont Division for
Historic Preservation

Description: View south including the south
side of the Village Green and Buildings #1,2,
and 3

Photo: #3

82-A-190



82-A-190

Jericho Center Historic District

Jericho, Vermont

Credit: Gina Campoli

Date: August 1982

Negative filed at Vermont Division for
Historic Preservation

Description: View north including the Village
Green and Buildings #21 & 22

Photo: #4



82-A-191

Jericho Center Historic District

Jericho, Vermont

Credit: Gina Campoli

Date: August 1982

Negative filed at Vermont Division for
Historic Preservation

Description: View east including the Village
Green and buildings #24A, & 25

Photo: #5



Jericho Center Historic District

Jericho, Vermont

Credit: Gina Campoli

Date: August 1982

Negative filed at Vermont Division for
Historic Preservation

Description: View west, the Caswell Residence,
#1

Photo: #6

#1



Jericho Center Historic District

Jericho, Vermont

Credit: Gina Campoli

Date: August 1982

Negative filed at Vermont Division for
Historic Preservation

Description: View west, the Davis/Page
residence, #2

Photo: #7

82-A-189





82A-190

Jericho Center Historic District
Jericho, Vermont
Credit: Gina Campoli
Date: August 1982
Negative filed at Vermont Division for
Historic Preservation
Description: View southwest, the Old
Congregational Parsonage, #3
Photo: #8



82-A-189

Jericho Center Historic District
Jericho, Vermont
Credit: Gina Campoli
Date: August 1982
Negative filed at Vermont Division for
Historic Preservation
Description: View west, the Pliny Blackman
House, #4
Photo: #9



Jericho Center Historic District
Jericho, Vermont
Credit: Gina Campoli
Date: August 1982
Negative filed at Vermont Division for
Historic Preservation
Description: View northwest, door detail, the
Pliny Blackman House, #4
Photo: #10

82-A-191

#4 - detail



Jericho Center Historic District

Jericho, Vermont

Credit: Gina Campoli


Date: August 1982

Negative filed at Vermont Division for
Historic Preservation

Description: View west, Desso's store and
barn, #5 & 6

Photo: #11

82-A-189





82-A-189

Jericho Center Historic District

Jericho, Vermont

Credit: Gina Campoli

Date: August 1982

Negative filed at Vermont Division for
Historic Preservation

Description: View west, Desso's store barn,
#6

Photo: #12



82-A-189

Jericho Center Historic District
Jericho, Vermont
Credit: Gina Campoli
Date: August 1982
Negative filed at Vermont Division for
Historic Preservation
Description: View northwest, Gregory/Weaver
House and barn, #8 & 8A
Photo: #13

#8, 8A



Jericho Center Historic District

Jericho, Vermont

Credit: Gina Campoli

Date: August 1982

Negative filed at Vermont Division for
Historic Preservation

Description: View west, the Former Bostwick
Store, #9

Photo: #14





Jericho Center Historic District

Jericho, Vermont

Credit: Gina Campoli

Date: August 1982

Negative filed at Vermont Division for
Historic Preservation

Description: View northwest, Jacobs Residence
and barn, #10 & 11

Photo: #15

82-A-190





82-A-190

Jericho Center Historic District
Jericho, Vermont
Credit: Gina Campoli
Date: August 1982
Negative filed at Vermont Division for
Historic Preservation
Description: View northwest, Roistacher
Barn/Garage, #12
Photo: #16



82-A-189

Jericho Center Historic District
Jericho, Vermont
Credit: Gina Campoli
Date: August 1982
Negative filed at Vermont Division for
Historic Preservation
Description: View north, Elias Bartlett/
Roistacher House, #13
Photo: #17

#13



Jericho Center Historic District
Jericho, Vermont

Credit: Gina Campoli

Date: August 1982

Negative filed at Vermont Division for
Historic Preservation

Description: View northwest, door detail

Elias Bartlett - Roistacher House, #13

Photo: #18

82-7-189

#13-Door



Jericho Center Historic District

Jericho, Vermont

Credit: Gina Campoli

Date: August 1982

Negative filed at Vermont Division for
Historic Preservation

Description: View northeast, Abel Hoskins -
Shermer House, #14

Photo: #19

82-A-191

#14



82-A-190

Jericho Center Historic District
Jericho, Vermont
Credit: Gina Campoli
Date: August 1982
Negative filed at Vermont Division for
Historic Preservation
Description: View northeast, Orley Thompson -
Dickerson House, #16
Photo: #20



82-A-189

Jericho Center Historic District
Jericho, Vermont
Credit: Gina Campoli
Date: August 1982
Negative filed at Vermont Division for
Historic Preservation
Description: View southwest, Dickerson Barn,
#17
Photo: #21

#17



Jericho Center Historic District

Jericho, Vermont

Credit: Adele Cramer

Date: March 1977

Negative filed at Vermont Division for
Historic Preservation

Description: View northeast, Former
Universalist Church, #18

Photo: #22



Jericho Center Historic District
Jericho, Vermont
Credit: Gina Campoli
Date: August 1982
Negative filed at Vermont Division for
Historic Preservation
Description: View northeast, Former Jericho
High School, #19
Photo: #23

82-A-190

#19



82-A-191

Jericho Center Historic District
Jericho, Vermont
Credit: Gina Campoli
Date: August 1982
Negative filed at Vermont Division for
Historic Preservation
Description: View northeast, Towne Residence
#20
Photo: #24



Jericho Center Historic District
Jericho, Vermont
Credit: Gina Campoli
Date: August 1982
Negative filed at Vermont Division for
Historic Preservation
Description: View north, First Congregational
Church, #21
Photo: #25

82-A-190



Give
unto the
LORD the
glory due to his
name: worship
the LORD in the
beauty of holiness.

PLATE
187
183
370
419

They
that wait upon
the LORD shall
renew their strength:
I will make them
joyful in my
house of prayer.

Jericho Center Historic District
Jericho, Vermont
Credit: Adele Cramer
Date: February 1977
Negative filed at Vermont Division for
Historic Preservation
Description: Interior detail, First
Congregational Church, #21
Photo: #26

#21



Jericho Center Historic District
Jericho, Vermont
Credit: Adele Cramer
Date: February 1977
Negative filed at Vermont Division for
Historic Preservation
Description: Ceiling detail, First
Congregational Church, #21
Photo: #27

97-A-26



82-A-190

Jericho Center Historic District
Jericho, Vermont
Credit: Gina Campoli
Date: August 1982
Negative filed at Vermont Division for
Historic Preservation
Description: View northeast, Former Congrega-
tional Parsonage/Haywood Residence, #22
Photo: #28



82-A-190

Jericho Center Historic District
Jericho, Vermont

Credit: Gina Campoli

Date: August 1982

Negative filed at Vermont Division for
Historic Preservation

Description: View east, Haywood Barn, #23

Photo: #29



Jericho Center Historic District
Jericho, Vermont

Credit: Gina Campoli

Date: August 1982

Negative filed at Vermont Division for
Historic Preservation

Description: View southeast, Former
Congregational Parsonage/Dreibelbis House,
#24

Photo #30

#24

82-A-190



Jericho Center Historic District
Jericho, Vermont
Credit: Gina Campoli
Date: August 1982
Negative filed at Vermont Division for
Historic Preservation
Description: View southeast, Former
Jericho Academy, #25
Photo: #31

82-A-190



82-A-190

Jericho Center Historic District
Jericho, Vermont
Credit: Gina Campoli
Date: August 1982
Negative filed at Vermont Division for
Historic Preservation
Description: View Southeast, Murphy-
Arcand House and Barn, #26 and 26A
Photo: #32



82-A-190

Jericho Center Historic District
Jericho, Vermont
Credit: Gina Campoli
Date: August 1982
Negative filed at Vermont Division for
Historic Preservation
Description: View East, Coppersmith/
Sartore Residence, #27
Photo: #33