

Ancelin V. Lynch April, 1977 Rhode Island Historical Preservation Commission

Facade of the house from the west northwest.

JUN 281978

NOV 17 1978

#1



Ancelin V. Lynch April, 1977 Rhode Island Historical Preservation Commission

Close-up of doorway, from the west.

JUN 28 1918

#2

WOV 17 1978



Ancelin V. Lynch April, 1977 Rhode Island Historical Preservation Commission

Front parlor mantel, from the west southwest, also showing doorframe moulding at right and edge of built-in cupboard at left.

JUN 281978

#3 12124 1 7 1376



Ancelin V. Lynch April, 1977 Rhode Island Historical Preservation Commission

Kitchen fireplace, street level story, from the east:

JUN 281978

#4

NOV 1 7 1978



LORENZO CRANDALL HOUSE

221 High Street, Pawtucket, Rhode Island

Photographer: Ancelin Lynch Date: December, 1979 Negative filed at: Rhode Island Historical Preservation Commission 150 Benefit Street, Providence, RI

View north showing house ready to be moved; new site and foundation in the foreground.

Photo #1



LORENZO CRANDALL HOUSE 221 High Street, Pawtucket, Rhode Island

Photographer: Ancelin Lynch Date: December, 1979 Negative filed at: Rhode Island Historical Preservation Commission 150 Benefit Street, Providence

View north from new site and foundation to house raised on original site.

Photo #2



LORENZO CRANDALL HOUSE 221 High Street, Pawtucket, Rhode Island

Photographer: Bruce Tillinghast Date: June, 1982 Negative filed at: Bruce Tillinghast 221 High Street Pawtucket, Rhode Island

View of house looking northeast showing it in it new location with porches rebuilt.

Photo #3



LORENZO CRANDALL HOUSE 221 High Street, Pawtucket, Rhode Island

Photographer: Bruce Tillinghast Date: June, 1982 Negative filed at: Bruce Tillinghast 221 High Street Pawtucket, Rhode Island

View of the house from the northwest.

Photo #4

x Ale