		Page				
		NORTH DAKOTA CULTURAL RESOURCES SURVEY				
13		NORTH DAKOTA CULTURAL RESOURCES SURVEY Base Data Form				
	1.	County Grand Forks, North Dakota 2. Site Number CK34				
N	3.	Site Name (s) St. John's Block (commonly called Commercial Exchange)				
	4.	Type of Resource: A. Archaeological_Historicalx_Architecturalx_Paleontological_				
		B. District_Site_Buildingx_Structure_Object				
	5.	Map Reference: USGS Quad. Grand Forks, N. Dak-Minn, 7.5' 1963 (photorevs'd 1979)				
4	6.	Location: 2 N. Third St. Sec. 3 T 151 N / R 50 W.				
-		Plat: Original Townsite Block 24 Lot Front				
		UTMG: A. <u>14.647150.5309690</u> . B. <u>100' of Lot 6</u>				
		CD				
	7.	Access: visible				
		Location: the northeast corner of DeMers Avenue and North Third				
		Street				
		Acreage: less than one acre				
		Verbal boundary: lots listed above, 50 X 100 feet				
• •	8.	A. General description of site: this is a five-story, flat-roofed, brick and ashlar commercial structure of rectangular plan. The north wall of the building adjoins a one-story commer- cial building. The east wall adjoins a two-story commercial building. Set back the width of the sidewalk on the west and south, the building covers its entire lot. The basement is raised some four feet above grade, and basement windows are visible in the west and south facades of the building. (Cont.)				
		B. Condition of site: Fair				
	9.	Owner's name/address: Commercial Exchange Corp. 2 N.Third St. GF				
	10.	Occupant's name/address: Various 58201				
	11.	Historic Register value: Nat. State Undt. None On Reg. In District District				
	12.	Multiple Resource Open to public: Yes <u>x</u> No <u>1</u> 3. Preservation Underway: Yes <u>No</u> <u>X</u>				
	14.	Endangered by: Nothing				
	15.	Survey Project: Title_Hist, and Arch. Survey of G.F. ND Director_Norene and Joe				
		Other surveys in which included none Roberts				
	16.	Recommendations: being nominated to NRHP in MRN: Historic Resources of downtown				
		Grand Forks, North Dakota (Partial Inventory: Historic and ARchitectural Properti				
	17.	Environment: ElevationNearest Water: Type				
		NameDistanceDirection				
		Soil conditions:				
,		Soil Texture:				

Page

Environment, Cont.		Site Number	CK3
Ground Cover:		·	
Terrain:			
	n <mark>ann an San San San San San San San San S</mark>		
Local contact porces on organi	75+10n+		
Local contact person or organiz	Clident Contractor/10	uuraan ay ahaa ahaa ahaa ahaa ahaa ahaa aha	ويرونون المراجع المراجع المراجع المراجع
Photos: No_B/W_x Color_Prints_			
Contact Print: Roll 3,		Sec. 1.1	
8 X 10 Glossies: Roll 51			
Negatives stored at: Division o	r Archaeology and Hist	oric Preservation	
State Hist In space below attach and iden	tify a picture or cont	act print of the site	*
Sketch Map of Site:	Scale:		
	Ř.		
	ie naarde saat oost die staat nie deel staat nie gewaarde en op die die gewaarde en die oorgeneers en die die n In die deel die staat die staat nie die staat nie die staat die staat die staat die staat die staat die staat d		
	and the second		
		, 1	
	ODAK SAFETY FILM 5062		
		l. 1	
			E
W			£1.e
	THE TOTAL SIN		
1 1			
		•	
	<u>S</u> .	՟՟ ֈֈՠֈֈֈֈֈֈֈֈֈֈֈֈֈֈֈֈֈֈֈֈֈֈֈֈֈֈֈֈֈֈֈֈֈ	
	5		
Recorded by: <u>C. Kudzia</u>	0 - 90-000 - 000 - 000 - 000 - 000 - 000 - 000 - 000 - 000 - 000 - 000 - 000 - 000 - 000 - 000 - 000 - 000 - 000	Date	ly.

					Page 3	
		Continuation form:	His	toric Sites	Site Number <u>CK34</u>	
	The	matic categoryArchitecture/Commer	rce28. Date or period <u>1890-1891</u>			
	Structures: Number standing		Number collapsed			
i			Number of earthworks			
	Number of basement depressions			No structural remains observed		
	Architectural/Structural Detail:					
A	A.	Style or design <u>Richardsonian</u> r	omar	nesque		
	Β.	Architect/engineer				
	C.	Contractor/builder				
	D.	Original use <u>Commercial</u>	•••••••			
	E.	Present use <u>Commercial</u>				
	F.	Number of stories 5			spårtial	
1	Н.	Foundation Material <u>Sandstone</u>	1			
	Ι.	Wall Construction Brick				
	ე.	Wall Treatment Sandstone, 1st st	ory	; brick, upper	stories	
	К.	Roof type and material Flat				
	L.	Number of bays: Front <u>3</u> Side <u>4</u>	14.	Plan shape Rec	tangular	
	Fro	ntage <u>50'</u>	32.	Distance from r	oad 00	
ļ	Num	ber of outbuildings	34.	Description of	outhuildings	

35. Changes

36. Information sources/References

See GF17, Security Trust Building.

37. Reason for significance:

See GF17, Security Trust Building.

Recorded byC. Kudzia	Date 7/81
	Date 9/81

Page 4

NORTH DAKOTA CULTURAL RESOURCES SURVEY

Continuation form

Site Number CK34

Item No. 8.A. General description of site (Cont.)

8.A. The first story and raised basement of the south and west (principal) elevations of the Commercial Exchange are faced in rusticated grey granite. The west elevation features colonettes flanking the transom of the main entry. Both main and side entries include transoms above the doors which are divided into three parts by rusticated stone mullions. The transom windows are set in deep reveals formed by the stone mullions and lintels. Most of the display windows on the main story are simple picture windows with three part fixed lights above. Two of these windows (one on the east and one on the west) incorporate one-over-one, double-hung side windows which were originally single expanses of glass.

The second, third, and fourth stories are composed of window bays separated vertically by red brick pilaster strips and horizontally by red brick spandrels. Windows are two-over-two, double-hung. Each window bay has a rusticated granite sill and lintel course. Granite courses band the building at the top and bottom of the pilaster strips. The fifth floor windows are tied by continuous, rusticated granite sill and lintel courses. Rounded brick colonnades divide the window bays. Above the fifth floor, there is a bracketed cornice of rusticated granite, and above that a parapet with inset brickwork suggests a colonnaded parapet. Pilaster strips extend beyond the roofline and are capped with rusticated granite.

The north facade of this building is faced with common yellow brick. It is unornamented.