



Sheldon House
458 Scituate Avenue
Cranston, Rhode Island

Photographer: Vivian Lasky

Date: June, 1987

Negative: Rhode Island Historical
Preservation Commission

View: Exterior, northeast corner showing east (front) and
north (side elevations).

Photo #1

6/21/88



Sheldon House
458 Scituate Ave
Cranston, Rhode Island

Photographer: Vivian Lasky

Date: June, 1987

Negative: Rhode Island Historical
Preservation Commission.

View: Exterior, east elevation, front door.

Photo #2

6/21/88



Sheldon House
458 Scituate Avenue
Cranston, Rhode Island

Photographer: Vivian Lasky

Date: June, 1987

Negative: Rhode Island Historical
Preservation Commission

View: Exterior, east elevation, showing south end of
main house and east side of kitchen ell.

Photo #3

6/26/87



Sheldon House
458 Scituate Avenue
Cranston, Rhode Island

6/21/87

Photographer: Vivian Lasky

Date: June, 1987

Negative: Rhode Island Historical
Preservation Commission

View: Interior, fireplace, front chamber (dining room)

Photo # 4



Sheldon House
458 Scituate Avenue
Cranston, Rhode Island

Photographer: Lynn Furney

Date: February, 1988

Negative: Rhode Island Historical
Preservation Commission

View: Summer Kitchen, southern ell.

Photo # 5

#5

2/21/88



Sheldon House
458 Scituate Avenue
Cranston, Rhode Island

Photographer: Vivian Lasky

Date: June, 1987



Negative: Rhode Island Historical
Preservation Commission.

View: Interior, fireplace wall, northeast parlor.

Photo # 6

46

6/21/88



Sheldon House
458 Scituate Avenue
Cranston, Rhode Island

Photographer: Lynn Furney

Date: February, 1988

Negative: Rhode Island Historical
Preservation Commission

View: Original Kitchen, now south parlor.

Photo #7

6/21/88