



① J.C. STRIBLING BARN
CLEMSON, PICKENS CO., S.C.
WEST ELEVATION



② J.C. STRIBLING BARN
CLEMSON, PICKENS CO., S.C.
WEST ELEVATION



③ J. C. STRIBLING BARN
CLEMSON, PICKENS CO., S. C.
WEST & NORTH ELEVATIONS



④ J. C. STRIBLING BARN
CLEMSON, PICKENS Co., S. C.
NORTH ELEVATION



⑤ J. C. STRIBLING BARN
CLEMSON, PICKENS CO., S. C.
WEST & NORTH ELEVATIONS



⑥ J. C. STRIBLING BARN
CLEMSON, PICKENS CO., S.C.
NORTH ELEVATION, ROOF DETAIL



⑦ J. C. STRIBLING BARN
CLEMSON, PICKENS CO., S. C.
WEST & SOUTH ELEVATIONS



⑧ J. C. STRIBLING BARN
CLEMSON, PICKENS CO., S.C.
WEST & SOUTH ELEVATIONS



⑨ J. C. STRIBLING BARN
CLEMSON, PICKENS CO., S. C.
WEST ELEVATION



⑩ J. C. STRIBLING BARN
CLEMSON, PICKENS CO., S.C.
SOUTH (REAR) ELEVATION



⑪ J. C. STRIBLING BARN
CLEMSON, PICKENS CO., S. C.
WEST SIDE OF CLERESTORY



⑫ J. C. STRIBLING BARN
CLEMSON, PICKENS CO., S.C.
WEST SIDE OF CLERESTORY



⑬

J.C. STRIBLING BARN

CLEMSON, PICKENS CO., S.C.

DETAIL OF CROSS-PEDIMENTED GABLE ENTRANCE



14

J. C. STRIBLING BARN
CLEMSON, PICKENS CO., S.C.

DETAIL OF PEDIMENTED

CROSS-GABLE ENTRANCE



①⑤

J. C. STRIBLING BARN
CLEMSON, PICKENS CO., S.C.
DETAIL OF CROSS-PEDIMENTED
GABLE ENTRANCE



①⑥ J. C. STRIBLING BARN
CLEMSON, PICKENS CO., S.C.
DETAIL OF CROSS-PEDIMENTED
GABLE ENTRANCE



①⑦ J. C. STRIBLING BARN
CLEMSON, PICKRENS CO., S. C.
DETAIL OF CUSTOM BRICK ON WEST ELEVATION



⑩ J. C. STRIBLING BARN
CLEMSON, PICKENS CO., S.C.
DETAIL OF INTERIOR ROOF FRAMING



①9

J. C. STRIBLING BARN
CLEMSON, PICKENS CO., S.C.

DETAIL OF INTERIOR ROOF FRAMING



② J.C. STRIBLING BARN
CLEMSON, PICKENS CO., S.C.
DETAIL OF INTERIOR ROOF FRAMING



② J. C. STRIBLING BARN
CLEMSON, PICKENS CO., S.C.
DETAIL OF INTERIOR ROOF FRAMING