



1. Kelsey House, Newington, Connecticut  
"Doomed for destruction"  
March 22, 1979. Photographer, Kevin J. Meehan  
Negative on file at Newington Historical Society and Trust, Inc.



- 
2. Kelsey House, Newington, Connecticut  
On new site, 1700 Main St.  
August 16, 1980. Photographer, Kevin J. Meehan  
Negative on file at Newington Historical Society and Trust, Inc.



3. Kelsey House, Newington, Connecticut  
Restoration in progress  
August 16, 1980. Photographer, Kevin J. Meehan  
Negative on file at Connecticut Historical Commission



4. Kelsey House, Newington, Connecticut  
Parlor mural, "Cottage on a hill"  
July 24, 1981. Photographer, Kevin J. Meehan  
Negative on file at Newington Historical Society and Trust, Inc.






5. Kelsey House, Newington, Connecticut  
Parlor mural, "Pastoral with harbor view"  
July 24, 1981. Photographer, Kevin J. Meehan  
Negative on file at Newington Historical Society and Trust, Inc.



6. Kelsey House, Newington, Connecticut  
Parlor mural, "Winter scene"  
July 24, 1981. Photographer, Kevin J. Meenan  
Negative on file at Newington Historical Society and Trust, Inc




7. Kelsey House, Newington, Connecticut  
Detail of west chamber wall, motif about 14 inches each side.  
July 24, 1981. Photographer, Kevin J. Meehan  
Negative on file at Newington Historical Society and Trust, Inc.



8. Kelsey House, Newington, Connecticut  
West chamber frieze and border designs  
July 24, 1981. Photographer, Kevin J. Meehan  
Negative on file at Newington Historical Society and Trust, Inc.






9. Kelsey House, Newington, Connecticut  
Detail of pattern repeated on east chamber walls, about true size.  
July 24, 1981. Photographer, Kevin J. Meehan  
Negative on file at Newington Historical Society and Trust, Inc.



10. Kelsey House, Newington, Connecticut  
Southwest parlor fireplace with cushion frieze, reeded dentils, and  
overmantel wallpainting.  
July 24, 1981. Photographer, Kevin J. Meehan  
Negative on file at Newington Historical Society and Trust, Inc.



11. Kelsey House, Newington, Connecticut  
Fireplace wall in dining room, with narrow cupboard, dentil-  
trimmed cornice, split lath ceiling.  
July 24, 1981. Photographer, Kevin J. Meehan  
Negative on file at Newington Historical Society and Trust, Inc.



12. Kelsey House, Newington, Connecticut.  
Narrow enclosed staircase in kitchen.  
July 24, 1981. Photographer, Kevin J. Meehan  
Negative on file at Newington Historical Society and Trust, Inc.





13. Kelsey House, Newington, Connecticut  
Fireplace and beehive oven in kitchen with  
paneled wall partially exposed.  
July 24, 1981. Photographer, Kevin J. Meehan  
Negative on file at Newington Historical Society and Trust, Inc.