

1. United Methodist Church  
Greenwich, CT

View: Facade and southwest elevation

Facing: N

Negative on file: Conn. Hist. Commission

Cunningham Associates

1/88



2. United Methodist Church  
Greenwich, CT

View: Church and parsonage

Facing: E

Negative on file: Conn. Hist. Commission

Cunningham Associates

1/88



3. United Methodist Church  
Greenwich, CT

View: Northeast elevation of church

Facing: S

Negative on file: Conn. Hist. Commission

Cunningham Associates

1/88



OUR HOUSE

10

88 1 6

4. United Methodist Church  
Greenwich, CT

View: Facade of parsonage

Facing: NW

Negative on file: Conn. Hist. Commission

Cunningham Associates

1/88



WENNICH  
S.D. PARKING

WENNICH  
S.D. PARKING

88 1 6

5. United Methodist Church  
Greenwich, CT

View: Southwest and rear elevations of  
parsonage and addition

Facing: E

Negative on file: Conn. Hist. Commission

Cunningham Associates

1/88



6. United Methodist Church  
Greenwich, CT


View: Interior nave of church

Facing: NW

Negative on file: Conn. Hist. Commission

Cunningham Associates

1/88



7. United Methodist Church  
Greenwich, CT

View: Interior nave of church

Facing: W

Negative on file: Conn. Hist. Commission

Cunningham Associates

1/88



8. United Methodist Church  
Greenwich, CT


View: Interior foyer of church

Facing: SW

Negative on file: Conn. Hist. Commission

Cunningham Associates

1/88



9 1 08,

9. United Methodist Church  
Greenwich, CT

View: Staircase in south corner

Facing: S

Negative on file: Conn. Hist. Commission

Cunningham Associates

1/88



10. United Methodist Church  
Greenwich, CT

View: Posts and braces in nave

Facing: W

Negative on file: Conn. Hist. Commission

Cunningham Associates

1/88



11. United Methodist Church  
Greenwich, CT

View: Interior parsonage east and north  
parlors (typical)

Facing: W

Negative on file: Conn. Hist. Commission

Cunningham Associates

1/88