

St. Paul, Minneapolis and Manitoba
Railway Company Shops
St. Paul, Ramsey County, MN
William F. Dunwiddie
7/22/86
Negative: Miller Dunwiddie Associates
3601 W. 77th St., Suite 850
Minneapolis, MN 55435
Facing south-west showing the east
and west elevations of (from left
to right) the Machine Shop, the
Pattern Shop and Storehouse
Negative # 8532 - A/3A



St. Paul, Minneapolis and Manitoba
Railway Company Shops
St. Paul, Ramsey County, MN
William F. Dunwiddie
7/22/86
Negative: Miller Dunwiddie Associates
3601 W. 77th St., Suite 850
Minneapolis, MN 55435
Facing north-east showing the west
and south elevations of (from
left to right) the Storehouse,
the Pattern Shop and the
Machine Shop.
Negative # 8532 - B/10A

L



St. Paul, Minneapolis and Manitoba
Railway Company Shops
St. Paul, Ramsey County, MN
William F. Dunwiddie
7/22/86
Negative: Miller Dunwiddie Associates
3601 W. 77th St., Suite 850
Minneapolis, MN 55435
Facing north-west showing the south
and east elevations of (from
left to right) the Pattern Shop,
the Storehouse and the partial
west elevation of the Machine Shop.
Negative # 8532 - B/32A



St. Paul, Minneapolis and Manitoba
Railway Company Shops
St. Paul, Ramsey County, MN
William F. Dunwiddie
7/22/86
Negative: Miller Dunwiddie Associates
3601 W. 77th St., Suite 850
Minneapolis, MN 55435
Facing north-east showing the west
and south elevations of (from
left to right) the Shorehouse,
the Pattern Shop and the
Machine Shop
Negative # 8532 - B/18A

U



St. Paul, Minneapolis and Manitoba
Railway Company Shops
(Machine Shop)
St. Paul, Ramsey County, MN
William F. Dunwiddie
7/22/86
Negative: Miller Dunwiddie Associates
3601 W. 77th St., Suite 850
Minneapolis, MN 55435
Facing north-east showing the west
elevation of the main building,
the west and south elevations of
the boiler addition, and the
main building
Negative # 8532 - A/18A



St. Paul, Minneapolis and Manitoba
Railway Company Shops
(Machine Shop)
St. Paul, Ramsey County, MN
William F. Dunwiddie
7/22/86
Negative: Miller Dunwiddie Associates
3601 W. 77th St., Suite 850
Minneapolis, MN 55435
Facing north-west showing the
south and east elevations
Negative # 8532 - A/1A



St. Paul, Minneapolis and Manitoba
Railway Company Shops
(Machine Shop)
St. Paul, Ramsey County, MN
William F. Dunwiddie
7/22/86
Negative: Miller Dunwiddie Associates
3601 W. 77th St., Suite 850
Minneapolis, MN 55435
Facing south-west showing the east
and north elevations
Negative # 8532 - A/2A



St. Paul, Minneapolis and Manitoba
Railway Company Shops
(Machine Shop)
St. Paul, Ramsey County, MN
William F. Dunwiddie
7/22/86
Negative: Miller Dunwiddie Associates
3601 W. 77th St., Suite 850
Minneapolis, MN 55435
Facing west showing detail of
reconstructed door (Note: Strap
hinges to be applied)
Negative # 8532 - A/24A



St. Paul, Minneapolis and Manitoba
Railway Company Shops
(Machine Shop)
St. Paul, Ramsey County, MN
William F. Dunwiddie
7/22/86
Negative: Miller Dunwiddie Associates
3601 W. 77th St., Suite 850
Minneapolis, MN 55435
Facing east showing detail of
reconstructed triple-hung
wood window and stone sill
Negative # 8532 - A/25A



St. Paul, Minneapolis and Manitoba
Railway Company Shops
(Machine Shop)
St. Paul, Ramsey County, MN
William F. Dunwiddie
7/22/86
Negative: Miller Dunwiddie Associates
3601 W. 77th St., Suite 850
Minneapolis, MN 55435
Facing north showing the interior
of the main portion of the
building while under construction
Negative # 8532 - A/33A



St. Paul, Minneapolis and Manitoba
Railway Company Shops
(Pattern Shop)
St. Paul, Ramsey County, MN
William F. Dunwiddie
7/22/86
Negative: Miller Dunwiddie Associates
3601 W. 77th St., Suite 850
Minneapolis, MN 55435
Facing north-east showing (from
left to right) a partial south

Facing north-east showing (from left to right) a partial south elevation of the Storehouse, the west and south elevations of the Pattern Shop and a partial west elevation of the Machine Shop

Negative # 8532 - A/9A



St. Paul, Minneapolis and Manitoba Railway Company Shops (Pattern Shop) St. Paul, Ramsey County, MN

William F. Dunwiddie 7/22/86

Negative: Miller Dunwiddie Associates 3601 W. 77th St., Suite 850 Minneapolis, MN 55435


Facing south-west showing the east and north elevations
Negative # 8532 - A/7A



St. Paul, Minneapolis and Manitoba
Railway Company Shops
(Pattern Shop)
St. Paul, Ramsey County, MN
William F. Dunwiddie
7/22/86
Negative: Miller Dunwiddie Associates
3601 W. 77th St., Suite 850
Minneapolis, MN 55435
Facing north showing a detail of a
reconstructed double-hung wood
window
Negative # 8532 - B/9A



St. Paul, Minneapolis and Manitoba
Railway Company Shops
(Pattern Shop)
St. Paul, Ramsey County, MN
William F. Dunwiddie
7/22/86
Negative: Miller Dunwiddie Associat
3601 W. 77th St., Suite 850
Minneapolis, MN 55435
Facing east showing the interior
while under construction
Negative # 8532 - A/36A



St. Paul, Minneapolis and Manitoba
Railway Company Shops
(Storehouse)
St. Paul, Ramsey County, MN
William F. Dunwiddie
7/22/86
Negative: Miller Dunwiddie Associates
3601 W. 77th St., Suite 850
Minneapolis, MN 55435
Facing north-west showing the
south and east elevations
Negative # 8532 - A/28A



St. Paul, Minneapolis and Manitoba Railway Company Shops (Storehouse)

St. Paul, Ramsey County, MN William F. Dunwiddie 7/22/86

Negative: Miller Dunwiddie Associa 3601 W. 77th St., Suite 850 Minneapolis, MN 55435

Facing north-east showing (from left to right) the west and sou' elevations of the Storehouse, th west and south elevations of the Pattern Shop, and a partial west elevation of the Machine Shop Negative # 8532 - A/14A



St. Paul, Minneapolis and Manitoba
Railway Company Shops
(Storehouse)
St. Paul, Ramsey County, MN
William F. Dunwiddie
7/22/86
Negative: Miller Dunwiddie Associates
3601 W. 77th St., Suite 850
Minneapolis, MN 55435
Facing south-east showing the north
and west elevations
Negative # 8532 - A/11A



St. Paul, Minneapolis and Manitoba
Railway Company Shops
(Storehouse)
St. Paul, Ramsey County, MN
William F. Dunwiddie
7/22/86
Negative: Miller Dunwiddie Associates
3601 W. 77th St., Suite 850
Minneapolis, MN 55435

Facing south-west showing (from left to right) the east and a portion of the north elevations of the Pattern Shop and the east and north elevations of the Storehouse

Negative # 8532 - A/4A



St. Paul, Minneapolis and Manitoba
Railway Company Shops
(Storehouse)
St. Paul, Ramsey County, MN
William F. Dunwiddie
7/22/86
Negative: Miller Dunwiddie Associates
3601 W. 77th St., Suite 850
Minneapolis, MN 55435
Facing west showing the interior
of the first floor while under
construction
Negative # 8532 - B/4A



St. Paul, Minneapolis and Manitoba
Railway Company Shops
(Storehouse)
St. Paul, Ramsey County, MN
William F. Dunwiddie
7/22/86
Negative: Miller Dunwiddie Associates
3601 W. 77th St., Suite 850
Minneapolis, MN 55435
Facing east showing the interior
of the second floor while under
construction
Negative # 8532 - B/7A

d