



Juniper Hill Farm-Maxwell Evarts House

Windsor, Vermont

Credit: Deborah Noble

Date: March, 1986

Negative: Filed at Vermont Division for

Historic Preservation

Description: #1; View Looking North

Photograph #1



Juniper Hill Farm—Maxwell Evarts House

Windsor, Vermont

Credit: Deborah Noble

Date: March, 1986

Negative Filed at Vermont Division for
Historic Preservation

Description: Detail of main entrance
for house; View Looking North

Photograph #2



Juniper Hill Farm—Maxwell Evarts House
Windsor, Vermont

Credit: Deborah Noble

Date: March, 1986

Negative Filed at Vermont Division for
Historic Preservation

Description: Rear of House #1, 1A, 1B,
1C; View Looking South

Photograph #3



Juniper Hill Farm—Maxwell Evarts House
Windsor, Vermont

Credit: Deborah Noble

Date: March, 1986

Negative Filed at Vermont Division for
Historic Preservation

Description: Southwest corner of house
#1 & 1A; View Looking Northeast

Photograph #4



Juniper Hill Farm—Maxwell Evarts House
Windsor, Vermont

Credit: Deborah Noble

Date: March, 1986

Negative Filed at Vermont Division for
Historic Preservation

Description: Southeast corner of house
#1 & 1B; View Looking Northwest

Photograph #5



Juniper Hill Farm-Maxwell Evarts House
Windsor, Vermont
Credit: Deborah Noble
Date: March, 1986
Negative Filed at Vermont Division for
Historic Preservation
Description: Hall of house
View Looking Northeast
Photograph #6



Juniper Hill Farm-Maxwell Evarts House

Windsor, Vermont

Credit: Deborah Noble

Date: March, 1986

Negative Filed at Vermont Division for
Historic Preservation

Description: Dining room fireplace

View Looking Southwest

Photograph #7



Juniper Hill Farm—Maxwell Evarts House

Windsor, Vermont

Credit: Deborah Noble

Date: April, 1986

Negative Filed at Vermont Division for
Historic Preservation

Description: Library stairway

View Looking Southeast

Photograph #8



Juniper Hill Farm-Maxwell Evarts House
Windsor, Vermont

Credit: Deborah Noble

Date: March, 1986

Negative Filed at Vermont Division for
Historic Preservation

Description: Carriage Barn #2

View Looking North

Photograph #9



Juniper Hill Farm-Maxwell Evarts House

Windsor, Vermont

Credit: Deborah Noble

Date: March, 1986

Negative Filed at Vermont Division for
Historic Preservation

Description: Carriage Barn rear

View Looking Southeast

Photograph #10



Juniper Hill Farm—Maxwell Evarts House
Windsor, Vermont

Credit: Deborah Noble

Date: April, 1986

Negative Filed at Vermont Division for
Historic Preservation

Description: Milkhouse #3

View Looking Northeast

Photograph #11



Juniper Hill Farm-Maxwell Evarts House
Windsor, Vermont

Credit: Deborah Noble


date: April, 1986

Negative Filed at Vermont Division for
Historic Preservation

Description: Silo foundation #4

View Looking West

Photograph #12



Juniper Hill Farm-Maxwell Evarts House
Windsor, Vermont

Credit: Deborah Noble

Date: April, 1986

Negative Filed at Vermont Division for
Historic Preservation

Description: Pumphouse #8

View Looking North

Photograph #13