

B. Clouette Photo, 1/82 Negative filed with Conn. Hist. Comm., Hartford

Facade (West Main Street elevation), view northeast



B. Clouette Photo, 1/83 Negative filed with Conn. Hist. Comm., Hartford


Washington Street (west) elevation, view southeast #2



B. Clouette Photo, 1/83Negative filed with Conn.Hist. Comm., HartfordDetail, facade, east store-

#3

front, view north



B. Clouette Photo, 1/83 Negative filed with Conn. Hist. Comm., Hartford

Floor tiling, front hallway #4




B. Clouette Photo, 1/83 Negative filed with Conn. Hist. Comm., Hartford

Lobby, view southwest



B. Clouette Photo, 1/83 Negative filed with Conn. Hist. Comm., Hartford

Main stairway, lobby, view south #6



B. Clouette Photo, 1/83 Negative filed with Conn. Hist. Comm., Hartford

Typical hotel room, showing door trim around entrance from corridor





COFFEE ROOM AND SODA BAR.

B. Clouette Photo, 1/83 Negative filed with Conn. Hist. Comm., Hartford

Postcard view, looking northeast, c.1925