

R. Myers August 1976 187 Market Street, Lexington

Photo 1. West (main) front.

JUL 12 1977

PROPERTY OF THE NATIONAL REGISTER



R. DeCamp August 1976

JUL 12 1977

187 Market Street, Lexington

Photo 2.7 Oriel window on center

Photo 2. Oriel window on center of second-floor facade, and arch of main entrance below. Note ribs of flat vault in open vestibule.



JAN 9 1978

R. DeCamp August 1976 187 Market Street, Lexington


Photo 3. Detail of veranda posts and spandrels, first-floor window frame.



JAN 9 1978

R. DeCamp, August 1976 187 Market Street, Lexington

Photo 4. View from interior of veranda with kitchen wing in background.



JAN 9 1978

R. DeCamp August 1976 187 Market Street, Lexington

Photo 5.7 Vergeboard and ventilator opening on main gable of Elley Villa.



R. DeCamp August 1976 187 Market Street, Lexington

Photo 6. Detail of subsidiary gable on second floor, with triple window.



JAN 9 1978

R. DeCamp August 1976 187 Market Street, Lexington

Photo 7.7 Triple chimney stacks on Elley Villa.




JAN 9 1978

R. Myers August 1976 187 Market Street, Lexington

Photo 8.9 Exterior view of library bay window in center of rear (east) elevation.

JUL 12 1977



JAN 9 1978

R. DeCamp August 1976 187 Market Street, Lexington

Photo 9. Mosaic design on floor of open vestibule.

JUL 12 1977

PROPERTY OF THE NATIONAL REGISTER





R. Myers August 1976 187 Market Street, Lexington

Photo 10. Interior view of hall showing front door and ceiling medallion. Also note frosted glass about the entrance.



JAN 9 1978

Lexington Herald-Leader 1960 Short Street, Lexington

Photo 11.0 Chandelier medallion in front hall.



JAN 9 1978

R. Myers August 1976 187 Market Street, Lexington

Photo 12.9 View of bay window in library, showing colored glass border.



JAN 9 1978

R. Myers August 1976 187 Market Street, Lexington

Photo 13.7 Marble mantel in right front parlor.

JUL 121977




R. Myers August 1976 187 Market Street, Lexington

JAN 9 1978

Photo 14. Marble mantel in dining room.

JUL 12 1977



R. Myers August 1976 187 Market Street, Lexington

Photo 15. Stairway.

JUL 12 1977 JAN 9 197