

Form No. 10-301a (Rev. 10-74) NATIONAL REGISTER

PROPERTY

UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

NATIONAL REGISTER OF HISTORIC PLACES PROPERTY PHOTOGRAPH FORM

FOR NPS USE ONLY RECEIVED

MAR 1 0 1975

SEE INSTRUCTIONS IN HOW TO COMPLETE NATIONAL REGISTER FORMS TYPE ALL ENTRIES **ENCLOSE WITH PHOTOGRAPH**

NAME

HISTORIC Silas Condict/ Joseph Cutler/ Augustus Cutler House

AND/OR COMMON Cutler Homestead

2 LOCATION

CITY, TOWN Morristown VICINITY OF

COUNTY

Morris

DATE ENTERED

STATE New Jersey

PHOTO REFERENCE

PHOTO CREDIT

Terry Karschner, Historic Sites Section

DATE OF PHOTO December, 1974

NEGATIVE FILED AT Dept. of Environmental Protection, Box 1420, Trenton, NJ

IDENTIFICATION

DESCRIBE VIEW, DIRECTION, ETC. IF DISTRICT, GIVE BUILDING NAME & STREET

PHOTO NO.

Camera facing northeast. View of the front and side facades of the main mid-19th century unit of the house. Earlier 19th century section is to the rear.



Form No. (7/72)	. 10-301a UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE			New Jersey		
		NATIONAL REGISTER OF HISTORI	CPLACES	Morris		
		PROPERTY PHOTOGRAPH FOR	FOR NPS USE ONLY			
S		(Type all entries - attach to or enclose wi	th photograph)	ENTRY NUMBER	DATE	
_				MAR 1 0 1975		
3.0	1. NAME					
0	Cutler Homestead			11112/		
1000	AND/OR HISTORIC:					
⊢ [2]	- 2. LOCATION / MECENTED X					
O D	SEP 24 1974					
2	Morristown Morristown CODE COUNTY: NATIONAL REGISTER CO					
S	STATE:	New Jersey	CODE COUNTY:	orris 6	© 96E	
z 3.	3. PHOTO REFERENCE					
_	рното credit: Ralph Cutler, Jr.					
	DATE OF PHOTO: 197)					
ш _	NEGATIVE FILED AT: R. Cutler, Red Gate Road, Morristown, NJ					
	4 IDENTIFICATION					
•••	DESCRIBE VIEW, DIRECTION, ETC.					
	Camera facing north. View of 1850's front facade.					
PROPERTY OF THE NATIONAL REGISTER						
	☆ U.S. GOVERNMENT PRINTING OFFICE: 1973-729-152/1446 Ⅲ-					



