

Photographer: James R. Lockhart

Negative filed: Georgia Department of Natural Resources Date: February, 1983 Description (1 of 10): South (front) and west sides of Exchange complex (red brick buildings), 1902 warehouse (with loading dock)in foreground; photographer facing northwest.



Photographer: James R. Lockhart Negative filed: Georgia Department of Natural Resources Date: February, 1983

Description (2 of 10): West side of Exchange complex along Washington Street, 1902 warehouse on left, 1932 warehouse on right; photographer facing west.



Photographer: James R. Lockhart Negative filed: Georgia Department

of Natural Resources
Date: February, 1983
Description (3 of 10): South side of 1902
warehouse with 1922 building in background;
photographer facing northwest.



Photographer: James R. Lockhart

Negative filed: Georgia Department of Natural Resources Date: February, 1983 Description (4 of 10): Rear (north side) of Exchange complex with 1922 building on right; photographer facing south.



Photographer: James R. Lockhart

Negative filed: Georgia Department of Natural Resources Date: February, 1983 Description (5 of 10): South (front) side of complex, 1922 headquarters building in foreground; photographer facing northeast.



Photographer: James R. Lockhart

Negative filed: Georgia Department of Natural Resources Date: February, 1983 Description (6 of 10): West side of 1922 Building; photographer facing northeast.



Photographer: James R. Lockhart

Negative filed: Georgia Department of Natural Resources Date: February, 1983 Description (7 of 10): First-floor interior of 1922 building; photographer facing northwest.



Photographer: James R. Lockhart

Negative filed: Georgia Department of Natural Resources Date: February, 1983 Description (8 of 10): First-floor office area in 1922 building; photographer facing northeast.



Photographer: James R. Lockhart
Negative filed: Georgia Department
of Natural Resources
Date: February, 1983
Description (9 of 10): Second-floor interior

of 1922 building; photographer facing

northwest.



Photographer: James R. Lockhart

Negative filed: Georgia Department of Natural Resources Date: February, 1983 Description (10 of 10): Construction detail, second floor of 1922 building; photographer facing toward ceiling.