

JUN 201977

McKay Photographers Maysville, Kentucky February 1977

Photo 1. View from northeast.



JUN 20 1977

McKay Photographers Maysville, Kentucky February 1977

DEC 20 1977

Photo 2. North facade.



Lee House
Maysville ·
Mason County JUN 2 0 1977
Kentucky

McKay Photographers Maysville, Kentucky February 1977

Photo 3. Doorway of north facade.



JUN 201977

DEC 20 1977

Gloria Mills February 1977 Kentucky Heritage Commission Frankfort, Kentucky

Photo 4. View from courtyard facing north.



JUN 201977

163 20 1977

McKay Photographers Maysville, Kentucky February 1977

Photo 5. Detail of one of twin winding staircases of northern section.



JUN 20 1977

McKay Photographers
Maysville, Kentucky
February 1977

DEC 2 0 1977

Photo 6. One of twin winding staircases of northern section.




DEC 20 1977

JUN 201977

McKay Photographers Maysville, Kentucky February 1977

Photo 7. View looking out to northern section's third floor balcony. Note width of door.



McKay Photographers Maysville, Kentucky February 1977

Photo 8. Brick-filled fireplace in oldest section's basement.

JE 2 2 191