



RESIDENCE OF DEACON JOHN HOLBROOK

Deacon John Holbrook House  
Brattleboro, Vermont

Credit: Unknown

Date: Prior to 1921

Picture from Annals of Brattleboro,  
Page 306 Front

Desc: Early Front View of House  
S. E. Corner

Photograph 1

DEC 3 1980



Deacon John Holbrook House  
Brattleboro, Vermont

Credit: James A. Britton

Date: September 1980

Negative Filed at Vt. Div. for  
Historic Preservation

Desc: Full View of Front Portico,  
S. E. Corner

Photograph 2

DEC 3 1980



Deacon John Holbrook House  
Brattleboro, Vermont

Credit: James A. Britton

Date: September 1980

Negative Filed at Vt. Div. for  
Historic Preservation

Desc: Rear View of House with  
First Floor Rear Porch. Later  
Entrance, right, (to be removed)  
Later Sleeping Porch, Second Floor  
(to be removed) S. W. View  
Photograph 3

DEC 3 1980



Deacon John Holbrook House  
Brattleboro, Vermont

Credit: James A. Britton

Date: September 1980

Negative Filed at Vt. Div. for  
Historic Preservation

Desc: Left Front Elevation of  
House, S. E. View

Photograph 4

DEC 3 1980





Deacon John Holbrook House  
Brattleboro, Vermont

Credit: James A. Britton

Date: September 1980

Negative Filed at Vt. Div. for  
Historic Preservation

Desc: Right Elev. of Entrance  
Portico Showing Front Entrance,  
N. E. View

Photograph 5

DEC 3 1980



Deacon John Holbrook House  
Brattleboro, Vermont

DEC 3 1980

Credit: James A. Britton

Date: September 1980

Negative Filed at Vt. Div. for  
Historic Preservation

Desc: South Wall of Living Room  
S. W. View

Photograph 6



Deacon John Holbrook House  
Brattleboro, Vermont


Credit: James A. Britton DEC 3

1980

Date: September 1980

Negative Filed at Vt. Div. for  
Historic Preservation

Desc: East Wall of Reception Room  
Showing Walnut Mirror and Surround-  
ing Hand-carved Woodwork, East View  
Photograph 7



Deacon John Holbrook House  
Brattleboro, Vermont

Credit: James A. Britton

Date: September 1980


Negative Filed at Vt. Div. for  
Historic Preservation

Desc: Woodwork Detail, S. E. Corner  
of Living Room, Indian Shutters at  
Window (painted in) to be Made  
Operative, S. E. View  
Photograph 8

DEC 3 1980

8  
3170





Deacon John Holbrook House  
Brattleboro, Vermont

Credit: James A. Britton

Date: September 1980

Negative Filed at Vt. Div. for  
Historic Preservation

Desc: Witches Stairs

Photograph 9

DEC 3 1980