

Location: Route 100 and Rockland Road

Photographer: J. Athan

Date: November 1977

Location of Negative: Div. of Hist. & Cultural Affairs

B/A&HP, Hall of Records, Dover, Delaware Description:

Southwestern Section of Blacksmith's Shop on Route 100

NEW CASHE County

1978



Location: Route 100 and Rockland Road
Montchanin, Delaware
Photographer: Jean Athan
Date: November 1977

Location of Negative: Div. of Hist. & Cultural Affairs B/Ashp, Hall of Records, Dover, Delaware Description:

Northern elevation of the "Pink Farm House" (N1086.20)

NEW CASTLE County

Photograph Number: 2 917

N-1086 (4)

IN 9 1978



#19

Names Montchanin Historic District JAN 10 1978

Location: Route 100 and Rockland Road

Montchanin, Delaware

Photographer: Jean Athan

Date: November 1977

Location of Negative: Divs. of Hist. & Cultural Affairs

B/A&HP, Hall of Records, Dover, Delaware

Description:

View south of N1086.19 and N1086.18 located at intersection of Rt. 100 & Kirk Road

New Castle County

Photograph Number: 3 417

N-1086 (3)



Location: Route 100 and Rockland Road

Montchanin, Delaware Photographer: J. Athan

Date: November 1977

Location of Negative: Div. of Hist. & Cultural Affairs

B/A&HP, Hall of Records, Dover, Delaware

Description:

Facade of 1086.17 which faces north onto Kirk Road
New Castle County

Photograph Numbers 4 317

N-1086 (5)

JUN 9 1978



JAN 1 0 1978

Name: Montchanin Historic District

Location: Route 100 and Rockland Road
Montchanin, Delaware
Photographer: Jean Athan
November, 1977

Lacation of Negative: Div. of Hist. & Cultural Affairs,

B/A&HP, Hall of Records, Dover, Delaware

View of the bank barn (N-1086.21) looking northeast

New Caste County

Photograph Number: 5 & 17

IN 9 1978



#16

Name: Montchanin Historic District JAN 101978

Location: Route 100 and Rockland Road

Montchanin, Delaware Photographer: J. Athan

Date: November 1977

Location of Negative: Div. of Hist. & Cultural Affairs,

B/A&HP, Hall of Records, Dover, Delaware Description:

View looking southwest at alley which enters into Montchanin's triangular complex.

NEW CASTIE COUNTY

Photograph Number: 6 %17

N-1086 (16)



JAN 1 0 1978

Name: Montchanin Historic District

Location: Route 100 and Rockland Road

Photographer: J. Athan

Date: November 1977

Location of Negative: Div. of Hist. & Cultural Affairs,

B/A&HP, Hall of Records, Dover, Delaware

Description:

View facing northeast: 20th century metal warehouse and converted brick warehouse which lies immediately to the north. NEW Costs

Photograph Number: 7 417

N-1086 (15)



Location: Route 100 and Rockland Road

Montchanin, Delaware Photographer: J. Athan

Date: November 1977

Location of Negative: Div. of Hist. & Cultural Affairs,

B/A&HP, Hall of Records, Dover, Del. Description:

View of eastern (rear) elevation of Montchanin Railroad Station with eastern side of Montchanin's triangular complex in the background. Photograph Number: % %17

N-1086 (14)



Location: Route 100 and Rockland Road

Photographer: J. Athan

Date: November 1977

Location of Negative: Div. of Hist. & Cultural Affairs

B/ASHP, Hall of Records, Dover, Delaware

Description:

View of northeastarea of complex of stucco duplexes, which are located on a private road. Shown are N-1086.9, N-1086.8 and N-1086.7.

Photograph Number: 9 817

NEW CASHE COUNTY

unty JUN 9



Location: Route 100 and Rockland Road

Montchanin, Delaware Photographer: J. Athan

Date: November 1977

Location of Nogative: Div. of Hist. & Cultural Affairs

B/A&HP, Hall of Records, Dover, Delaware

Description:

View from Rockland Road looking southwest at a brick warehouse which has been converted for commercial use (N1086.4) NEW CASHE COUNTY Photograph Number: N-1086 (12)



#15 - 16 JAN 10 1978

Montchanin Historic District Name:

Location: Route 100 and Rockland Road

Montchanin, Delaware Photographer: J. Athan

Date: November 1977

Location of Negative Div. of Hist. & Cultural Affairs

B/ASHP, Hall of Records, Dover, Delaware

Description:

Facing north two wood frame structures (N1086.15 and N1086.16) situated on western side of Rockland Road

New Castle County Photograph Number: 11 2017

N-1086 (11)



Montchanin Historic District Name:

Location: Route 100 and Rockland Road

Montchanin, Delaware

Photographer: J. Athan Date: November 1977

Location of Negative: Div. of Hist. & Cultural Affairs

B/A&HP, Hall of Records, Dover

Description:

View of two stucco duplexes (N-1086.13 and N-1086.14) on western side of Rockland Road, which face southeast.

NEW Castle County
Photograph Number: 12 & 17

N-1086 (10)



(, 1,8,9, 10 JAN 101978

Name: Montchanin Historic District

Location: Route 100 and Rockland Road
Montchanin, Delaware

Photographer: J. Athan

Date: November 1977

Location of Negative: Div. of Hist. & Cultural Affairs

B/A&HP, Hall of Records, Dover, Delaware

Description:

View facing east of brick garage and warehouse (N1086.6) and adjacent stucco duplexes (N1086.7 - N1086.10) within complex, located on a private road.

Photograph Number: 13 a 17

N-1086 (9) NEW Costle Count

IUN 9 1978



Location: Route 100 and Rockland Road

Montchanin, Delaware Photographer: J. Athan

Date: November 1977

Location of Negative; Div. of Hist. & Cultural Affairs B/A&HP, Hall of Records, Dover. Delaware

Description:

View of the one story carriage house (N1086.3) on southeast corner of Rt. 100 & Rockland Road with Montchanin triangular complex immediately to the north of it.

Photograph Number: 14 817

N-1086 (8) NEW Costle County

1978



Location: Rt. 100 and Rockland Road

Montchanin, Delaware Photographer: J. Athan

Date: November 1977

Location of Negative: Div. of Hist. & Cultural Affairs

B/A&HP, Hall of Records, Dover, Delaware

Description:

View of southern point of Montchanin's triangular complex on which stone schoolhouse (N1086.11) is situated.

NEW CASHE County Photograph Number: 15 9 17

N-1086 (7)



Location: Route 100 and Rockland Road Montchanin, Delaware Photographer: Joan Norton Date: 1973

Location of Negative: Div. of Hist. & Cultural Affairs

B/A&HP, Hall of Records, Dover, Delaware Description:

Rear View of Montchanin Railroad Station

New Castle County

Photograph Number: 16 \$17

1978



Montchanin Historic District Name:

Location: Route 100 and Rockland Road

Montchanin, Delaware Photographer: Joan Norton

Date: 1973

Location of Negative: Division of Hist. & Cultural Affairs

B/A&HP, Hall of Records, Dover, Delaware Description:

facade of the Montchanin Railroad Station which faces northwest onto Rockland Road.

NEW CASTE COUNTY Photograph Number: 17 a 17

N-1086 (1)