



Ross/Averill House
Brownsville, Linn Co., OR.

M. J. NELSON

ca. 1880

negative at SHPO; original photo
at Linn Co. Museum, Brownsville

View of "downtown" Brownsville
from east hill. Ross/Averill
House at extreme right.

1 of 9



Ross/Averill House

Brownsville, Linn Co, OR.

(photographer) P. D. ROSS, INFORMANT; DENNY ROSS INSCRIPTION ATTRIBUTES PHOTO TO
ca. 1890 HIS FATHER, WILLIAM F. ROSS.

SH PO (original photo at Linn Co., Museum, 101 Park Ave, Brownsville, OR)

West elevation, HJC Averill and family in foreground,

2 of 9



Ross/Averill House
Brownsville, Linn Co, OR
M.J. Nelson
July, 1990
negative at SHPO
West (front) elevation
3 of 9



Ross/Averill House

Brownsville, Linn Co, OR

M.J. Nelson

July 1990

negative at SHPO

north elevation

4 of 9



Ross/Averill House
Brownsville, Linn Co., OR.

m. J. Nelson

July 1990

negative at S470

East elevation

5 of 9



Ross/Averill House

Brownsville, Linn Co., OR.

M J Nelson

July 1990

negative at SHPO

Foundation detail/north elevation.

Shows stone pier, vertical planks
of box construction.

6 of 9



Ross/Averill House

Brownsville, Linn Co., OR.

m.J. Nelson

July 1990

negative at SHPO

Interior of dining room. Looking toward east (rear) door and stairway door. Shows original wainscoting, rimlock "scars" on doors, mopboard. Opening to kitchen at right.

7 of 9




Ross/Averill House
Brownsville, Linn Co., OR.
M. J. Nelson
July 1990
negative at SHPO.

Interior of living room, looking west.

Flat 1"x4" and bullnose trim on window.

8 of 9



Ross/Averill House
Brownsville, Linn Co., OR.

M.J. Nelson

July, 1990

negative at SHPO

Interior, west attic room looking
toward S.E. corner. Shows portion
of plank door, 1" quarter round corner
trim, flushboard wall surface, boxed
2"x4" which appears to be a construction
detail.

9 of 9