



86A14

Waits River Schoolhouse

Waits River, VT

Photo: Trish Bensinger

March 1986

Front perspective, view looking
east

Photograph 1

17908



86A14

Waits River Schoolhouse

Waits River, VT

Photo: Trish Benainger

March 1986

Front perspective, view looking
north

Photograph 2



86A14

Waits River Schoolhouse
Waits River, VT
Photo: Trish Bensinger
March 1986

Rear perspective, view looking
west
Photograph 3



86A14

Waits River Schoolhouse

Waits River, VT

Photo: Trish Bensinger

March 1986

Detail, banked windows on the
southeast elevation

Photograph 4



86A 14

Waits River Schoolhouse
Waits River, VT
Photo: Trish Bensinger
March 1986


Interior, 1st floor classroom,
banked windows looking east
Photograph 5



86A14

Waits River Schoolhouse
Waits River, VT
Photo: Trish Bensinger
March 1986

Interior, 1st floor classroom,
view looking north
Photograph 6



Waits River Schoolhouse
Waits River, VT
Photo: Trish Bensinger
March 1986

Detail, 1st floor classroom,
pressed metal ceiling and
wall cladding
Photograph 7

86A 14



86A14

Waits River Schoolhouse
Waits River, VT
Photo: Trish Bensinger
March 1986

Interior, 2nd floor classroom,
view looking east
Photograph 8