



Name: Achmester, N-3930

Location: Road 429; between Armstrong & Odessa; St. Georges
Hundred; New Castle County, Delaware
Photographer: Jean Athan, City of Wilm.

Date: 1978

Location of Negative: Div. of Historical & Cultural Affairs,
B/A&HP, Hall of Records, Dover, Delaware 19901

Description: facade

Photograph Number: 1 of 20

OCT 30 1979

DOE
28



Name: Achmester, N-3930

Location: Road 429; between Armstrong & Odessa; St. Georges
Hundred; New Castle County, Delaware

Photographer: Jean Athan

Date: 1978

Location of Negative: Div. of Historical & Cultural Affairs,
B/A&HP, Hall of Records, Dover, Delaware 19901

Description: 3/4 view showing rear service ell

OCT 30 1979

Photograph Number: 2 of 20

DOE

28



Name: Achmester, N-3930

Location: Road 429; between Armstrong & Odessa; St. Georges
Hd.; New Castle Co., Delaware

Photographer: Jean Athan, City of Wilm., Dept. of Planning
Date: 1978 & Development

Location of Negative: Div. of Hist. & Cult. Aff.; B.A.&H.R
Hall of Records, Dover, DE

Description: View of house from rear

Photograph Number: 3 of 20

OCT 30 1979

DOE
28



ACQUIESCER seat of the late RICHARD MANSFIELD

Name: Achmester, N-3930

Location: Rd. 429; between Armstrong & Odessa; St. Georges
Hd.; New Castle Co., Delaware.

Photographer: Mr. Henry Vaughn, & Div. of Hist. & Cult. AFF.

Date: 1979

Location of Negative: Div. of Hist. & Cult. Aff.; B.A. &
HR; Hall of Records, Dover, Delaware

Description: View of "Achmester, seat of the late Richard
Mansfield" from an oil painting, ca. 1850, in the
possession of Mr. Henry Vaughn.

Photograph Number: 4 of 20

OCT 30 1979

DEC 28

DOE



Name: Achmester, N-3930

Location: Rd. 429; between Armstrong & Odessa; St. Georges
Hd.; New Castle Co., Delaware.

Photographer: Jean Athan, City of Wilm., Dept. of Planning
& Development.

Date: 1978

Location of Negative: Div. of Hist. & Cult. Affairs;
B.A. & H.R.; Hall of Records, Dover, Delaware.

Description: Detail of western gable and of main block,
showing gothic revival decorative elements &
replaced siding.

Photograph Number: 5 of 20

OCT 30 1978

POE
28



Name: Achmester, N-3930

Location: Rd. 429; between Armstrong & Odessa; St. Georges
Hd.; New Castle Co., Delaware.

Photographer: Jean Athan, City of Wilm., Dept. of Planning

Date: 1978

& Development.

Location of Negative: Div. of Hist. & Cult. Affairs;

B.A. & H.R.; Hall of Records, Dover, Delaware.

Description: Detail of door and portico on gable wing,
at facade.

Photograph Number: 6 of 20

OCT 30 1979

DOE
28 1979



Name: Achmester, N-3930

Location: Rd. 429; between Armstrong & Odessa, St. Georges
Hd.; New Castle Co., Delaware.

Photographer: Jean Athan, City of Wilm., Dept. of Planning
Date: 1978 & Development.

Location of Negative: Div. of Hist. & Cult. Affairs;
B.A. & H.R.; Hall of Records, Dover, Delaware.

Description: Detail: facade door to main block.

Photograph Number: 7 of 20

OCT 30 1979

DEC 28 ^{DOE}



Name: Achmester, N-3930

Location: Rd. 429; between Armstrong & Odessa, St. Georges
Hd.; New Castle Co., Delaware.

Photographer: Dean Nelson, Bureau of Archaeology &

Date: 1979 Hist. Preservation

Location of Negative: Div. of Hist. & Cult. Affairs,
B.A. & H.R.; Hall of Records, Dover, Delaware.

Description: Interior; marble chimney piece, west
foom of main block.

OCT 30 1979

Photograph Number: 8 of 20

DOE
DEC 28



Name: Achmester, N-3930

Location: Rd. 429; between Armstrong & Odessa, St. Georges
Hd.; New Castle Co., Delaware.

Photographer: Dean Nelson, Bureau of Archaeology &

Date: 1979 Historic Preservation.

Location of Negative: Div. of Hist. & Cult. Affairs,

B.A. & H.R.; Hall of Records, Dover, Delaware.

Description: Interior: Six panel door; west room of main
block looking into center hall.

Photograph Number: 9 of 20

OCT 30 1979

DOE

DEC 28



Name: Achmester, N-3930

Location: Rd. 429; between Armstrong & Odessa, St. Georges
Hd.; New Castle Co., Delaware.

Photographer: Dean Nelson, Bureau of Archaeology &

Date: 1979 Hist. Preservation

Location of Negative: Div. of Hist. & Cult. Aff., B.A. &
H.R.; Hall of Records, Dover, Delaware.

Description: Interior: Federal chimney piece; east room
of main block.

OCT 30 1979

Photograph Number: 10 of 20

DOE
JLC 28



Name: Achmester, N-3930

Location: Rd. 429; between Armstrong & Odessa, St. Georges Hd., New Castle Co., Delaware.

Photographer: ~~Dean~~ Nelson, Bureau of Archaeology & Date: 1979 Hist. Preservation.

Location of Negatives: Div. of Hist. & Cult. Aff., B.A. & H.R.; Hall of Records, Dover, Delaware.

Description: Interior: small room in gable end wing; Federal chimney piece & closet door.

Photograph Number: 11 of 20

OCT 30 1979

008
DEC 28 1979



Name: Achmester, N-3930

Location: Rd. 429; between Armstrong & Odessa, St. Georges
Hd., New Castle Co., Delaware.

Photographer: Dean Nelson, Bureau of Archaeology &

Date: 1979 Hist. Preservation

Location of Negative: Div. of Hist. & Cult. Aff., B.A. &
H.R.; Hall of Records, Dover, Delaware.

Description: Interior: small room in gable end wing;
large closet door next to fireplace.

Photograph Number:

OCT 30 1979

12 of 20

DEC. 28 ^{DOE}



Name: Achmester, N-3930

Location: Rd. 429; between Armstrong & Odessa, St. Georges
Hd., New Castle Co., Delaware.

Photographer: Dean Nelson, Bureau of Archaeology &

Date: 1979 Hist. Preservation.

Location of Negative: Div. of Hist. & Cult. Aff., B.A. &
H.R.; Hall of Records, Dover, Delaware.

Description: Interior: large room in gable end section;
painted marble chimney piece.

Photograph Number: 13 of 20

OCT 30 1979

DOE
28 1979



Name: Achmester, N-3930

Location: Rd. 429; between Armstrong & Odessa, St. Georges
Hd., New Castle Co., Delaware.

Photographer: Dean Nelson, Bureau of Archaeology &

Date: 1979 Hist. Preservation.

Location of Negative: Div. of Hist. & Cult. Aff., B. A. &
H.R.; Hall of Records, Dover, Delaware.

Description: Interior: large room in gable end section;
double closet and stair to 2nd floor.

Photograph Number: 14 of 20

OCT 30 1979

DOE
DEC 28 1979



Name: Achmester, N-3930

Location: Rd. 429; between Armstrong & Odessa, St. Georges
Hd., New Castle Co., Delaware.

Photographer: Dean Nelson, Bureau of Archaeology &
Date: 1979 Hist. Preservation.

Location of Negative: Div. of Hist. & Cult. Aff., B.A. &
H.R.; Hall of Records, Dover, Delaware.

Description: Interior: 2nd Floor stair landing in
main block.

Photograph Number: 15 of 20

OCT 30 1979

DOE
DEC 28 1979



Name: Achmester, N-3930

Location: Rd. 429; between Armstrong & Odessa, St. Georges
Hd., New Castle Co., Delaware.

Photographer: Dean Nelson, Bureau of Archaeology &
Date: 1979 Hist. Preservation.

Location of Negative: Div. of Hist. & Cult. Aff., B.A. &
H.R.; Hall of Records, Dover, Delaware.


Description: Interior: room above west parlor in main
block; fireplace.

Photograph Number:

OCT 30 1979

16 of 20

DEC 28 1979
DOE



Name: Achmester, N-3930

Location: Rd. 429; between Armstrong & Odessa, St. Georges
Hd. New Castle Co., Delaware.

Photographer: Dean Nelson, Bureau of Archaeology &

Date: 1979 Hist. Preservation.

Location of Negative: Div. of Hist. & Cult. Affairs,
B.A. & H.R.; Hall of Records, Dover, Delaware.

Description: Interior: 2nd. floor, main block; beaded
corner post.

Photograph Number: 17 of 20

OCT 30 1979

DEC 28 1979 ^{DOE}



Name: Achmester, N.-3930

Location: Rd. 429; between Armstrong & Odessa, St. Georges
Hd., New Castle Co., Delaware.

Photographer: Dean Nelson, Bureau of Archaeology &

Date: 1979 Hist. Preservation.

Location of Negative: Div. of Hist. & Cult. Aff., B.A. &
H.R.; Hall of Records, Dover, Delaware.

Description: Interior: view of 4 panel door and 2nd
floor stair landing.

Photograph Number: 18 of 20

OCT 30 1979

DOE
DEC 28



Name: Achmester, N-3930

Location: Rd. 429; between Armstrong & Odessa, St. Georges
Hd., New Castle Co., Delaware.

Photographer: Jean Athan, , City of Wilm.,

Date: 1978

Location of Negative: Div. of Hist. & Cult. Aff., B/A&HP,
Hall of Records, Dover, Delaware.

Description: Outbuildings: barn, granery, silo, milk house,
water pump.

Photograph Number: 19 of 20

OCT 30 1979

DOE
DEC 28 1979



Name: Achmester, N-3930

Location: Rd. 429; between Armstrong & Odessa, St. Georges
Hd., New Castle Co., Delaware.

Photographer: Jean Athan

Date: 1978

Location of Negative: Div. of Hist. & Cult. Aff., B/A&HP'
Hall of Records, Dover, Delaware.

Description: Outbuilding: smokehouse of log construction.

Photograph Number: 20 of 20

OCT 30 1979

DOE
DEC 28 1979